


DEPT. NAT. RES & ENV



PE905009

**Figure 3:**  
Same field as Figure 2 but CL. The almost sutured grain contacts are clear.



**Figure 4: SWC 6, 3378m, 2mm, CL**  
The right-hand side of the field shows typical damaged (fractured) material with a fine-grained "matrix". On the left is better-preserved, more siliceous sandstone which shows numerous long and concavo-convex boundaries.