Well: **LONGTOM 3**

NOTE: Other sheets use this START DATE & TIME & POB Information in their setup

Starting POB: 88

Max POB on rig: 100

Start Date & Time: Mon 10-Jul-06 9:30

Forecast End Time: Fri 1-Sep-06 0:30

Forecast End Time :	Fri 1-Sep-06 0:30			
Start Time	Description	Target	Actual	Comments
	Tow rig to Longtom-3 from previous location.	15.00 hrs	9.50 hrs	Average tow speed 2.8 Kts
19:00 Mon 10 Jul	Mooring / Ballast	20.00 hrs	19.00 hrs	
14:00 Tue 11 Jul	Pre-spud preparation	6.00 hrs	0.00 hrs	
14:00 Tue 11 Jul	Run in hole with Drilling assembly Drill 36" hole	2.00 hrs 5.00 hrs	1.00 hrs 2.00 hrs	
15:00 Tue 11 Jul 17:00 Tue 11 Jul	Condition hole and displace to mud	1.00 hrs	0.50 hrs	
	POOH, Rack back BHA	1.00 hrs	1.00 hrs	
18:30 Tue 11 Jul	R/U WH / casing handling tools	4.00 hrs	0.50 hrs	
	PU and run 30", M/U WH RT	3.25 hrs	2.00 hrs	
21:00 Tue 11 Jul	Wait on weather to run 30" conductor	12.00 hrs	16.50 hrs	
13:30 Wed 12 Jul	Make conductor up to PGB, Run 30" on DP	3.00 hrs	4.50 hrs	
18:00 Wed 12 Jul	Circulate and cement 30"	2.00 hrs	2.50 hrs	
20:30 Wed 12 Jul	Wait on Cement	4.00 hrs	5.00 hrs	
01:30 Thu 13 Jul	POOH	0.25 hrs	1.00 hrs	
02:30 Thu 13 Jul	Make up cmt head/HPWH RT/BHA	6.00 hrs	4.50 hrs	
07:00 Thu 13 Jul	Trip In Hole to Drill Out 30" Shoe	1.00 hrs	1.00 hrs	
08:00 Thu 13 Jul	Drill Out Shoe	1.00 hrs	2.50 hrs	
10:30 Thu 13 Jul	Drill 22" hole to +/- 1010 m	34.00 hrs	36.00 hrs	Section TD of 1005m
22:30 Fri 14 Jul	Circulate & Condition Wellbore	2.00 hrs	2.00 hrs	
00:30 Sat 15 Jul	POOH/Rack back BHA	6.00 hrs	6.50 hrs	
07:00 Sat 15 Jul 08:30 Sat 15 Jul	Rig Up to Run 16" csg Run 16" Csg	9.00 hrs 20.75 hrs	1.50 hrs 12.50 hrs	
21:00 Sat 15 Jul	Run 16 Csg Run Drill Pipe Stinger	5.00 hrs	4.00 hrs	
01:00 Sat 15 Jul	Run 18 3/4" WH and 16" casing on DP, land and latch casing	1.50 hrs	1.50 hrs	
02:30 Sun 16 Jul	Circulate	1.00 hrs	1.00 hrs	
03:30 Sun 16 Jul	Cement 16" csg	4.00 hrs	4.00 hrs	
07:30 Sun 16 Jul	POOH with DP	3.00 hrs	2.00 hrs	
09:30 Sun 16 Jul	RU to run BOP & Riser	4.00 hrs	2.50 hrs	
12:00 Sun 16 Jul	Run Riser	6.00 hrs	7.00 hrs	
19:00 Sun 16 Jul	Install Slip jt and C & K lines	3.00 hrs	6.00 hrs	
	P/U SDL Ring and L/O BOP	1.00 hrs	4.00 hrs	
05:00 Mon 17 Jul	PT csg / H4 / C/K Valves	3.00 hrs	1.00 hrs	
06:00 Mon 17 Jul	Install Diverter	1.00 hrs	1.50 hrs	
07:30 Mon 17 Jul	R/D Riser running equipment	1.00 hrs	2.00 hrs	
09:30 Mon 17 Jul	M/U and stand back emergency hang off tool	0.50 hrs	0.50 hrs	
10:00 Mon 17 Jul	PU 14-3/4" bit & BHA	2.00 hrs	5.00 hrs	
15:00 Mon 17 Jul	RIH to 16" Shoe, picking up 5" DP	2.00 hrs	2.00 hrs	
17:00 Mon 17 Jul 19:00 Mon 17 Jul	Function test BOP RIH to 16" Shoe, picking up 5" DP	0.50 hrs 2.00 hrs	2.00 hrs 2.00 hrs	
21:00 Mon 17 Jul	Drill shoe track & 3m of hole	1.50 hrs	2.00 hrs	
23:00 Mon 17 Jul	Circ	1.00 hrs	1.00 hrs	
00:00 Tue 18 Jul	LOT	1.00 hrs	2.50 hrs	
02:30 Tue 18 Jul	POOH;Rack BHA	2.00 hrs	2.50 hrs	
	PU 9-1/2" bit & BHA	5.00 hrs		
10:00 Tue 18 Jul	RIH to 16" Shoe picking up 5" DP	5.00 hrs		
15:00 Tue 18 Jul	Displace Hole to SBM	4.00 hrs		Delay displacing SBM
19:00 Tue 18 Jul	Drill 9-1/2" Pilot Hole w/ RST/LWD	77.50 hrs		
00:30 Sat 22 Jul	CBU	6.00 hrs		
06:30 Sat 22 Jul	WT to Shoe	0.01 hrs		Optional
	POOH to Log	8.00 hrs		
14:30 Sat 22 Jul 17:30 Sat 22 Jul	RU E/Line	3.00 hrs		
17:30 Sat 22 Jul 01:30 Sun 23 Jul	E/Line log #1 E/Line log #2	8.00 hrs 12.00 hrs		
13:30 Sun 23 Jul	RD E/Line	2.00 hrs		
15:30 Sun 23 Jul	Plug-back to KOP	60.00 hrs		
03:30 Wed 26 Jul	Drill 13-1/2" Hole w/ RST	72.00 hrs		
03:30 Sat 29 Jul	Circulate	6.00 hrs		
09:30 Sat 29 Jul	Wiper Trip to 16" Shoe	8.00 hrs		
17:30 Sat 29 Jul	Circulate	4.00 hrs		
21:30 Sat 29 Jul	POOH	10.00 hrs		
07:30 Sun 30 Jul	RU to Run 10-3/4" Csg	2.00 hrs		
09:30 Sun 30 Jul	Run 10-3/4" csg	24.00 hrs		
	Make up CMT head / C&C & prep to CMT	2.00 hrs		
11:30 Mon 31 Jul	Cement 10-3/4" Csg	4.00 hrs		
15:30 Mon 31 Jul	Set casing hanger seals and P/T	2.00 hrs		
17:30 Mon 31 Jul	Release from casing hanger POOH	1.00 hrs		
18:30 Mon 31 Jul 19:30 Mon 31 Jul	RD casing hanger running Tools	1.00 hrs 2.00 hrs		
21:30 Mon 31 Jul	MU & run BOP test tools to ML	1.00 hrs		
22:30 Mon 31 Jul	Test BOPs	5.00 hrs		
	POOH w/ BOP test tool; LD	1.00 hrs		

04:30 Tue 01 Aug Make up BHA 8.00 hrs 12:30 Tue 01 Aug Rill to TD 10.00 hrs 12:30 Tue 01 Aug Rill to TD 10.00 hrs 13:30 Find 3 Aug GBU 11.00 hrs 13:30 Find 3 Aug GBU 11.00 hrs 13:30 Find 4 Aug Drill 9-1/2" Hole / LWD / RST to 2900m 33.00 hrs 13:30 Find 4 Aug Drill 9-1/2" Hole / LWD / RST to 3600m 33.00 hrs 13:30 Find 4 Aug Drill 9-1/2" Hole / LWD / RST to 3600m 33.00 hrs 13:30 Find 4 Aug Drill 9-1/2" Hole / LWD / RST to 3600m 33.00 hrs 15:30 Sun 06 Aug Round Trip 24.00 hrs 16:30 Mon 07 Aug Round Trip 25.00 hrs 16:30 Mon 07 Aug Drill 9-1/2" Hole / LWD / RST to 4600m 50.00 hrs 16:30 Mon 07 Aug Drill 9-1/2" Hole / LWD / RST to 4600m 50.00 hrs 16:30 Mon 07 Aug Round Trip 20.00 hrs 16:30 Mon 07 Aug Round Trip 20.00 hrs 16:30 Mon 10 Aug Round Trip 20.00 hrs 16:30 Sart 12 Aug Run 7" Liner 15:00 hrs 16:30 Sart 12 Aug Run 7" Liner 15:00 hrs 16:30 Sart 12 Aug Run 7" Liner 15:00 hrs 16:30 Sart 12 Aug Round Trip 15:00 hrs 16:00 hrs 16:30 Sart 12 Aug POOH with DP. scrape casing at approx 2160m 8.00 hrs 16:30 Sart 12 Aug POOH with DP. scrape casing at approx 2160m 8.00 hrs 16:30 Tun 17 Aug Run Bark Sc-1R Packer with FBIV on DP, sting into top of 7" Liner, set packer 14:00 hrs 16:00 hrs 17:30 Thu 17 Aug Run Bark Sc-1R Packer with FBIV on DP, sting into top of 7" Liner, set packer 12:00 hrs 16:00 hrs		<u></u>			
22:30 Tue of 1 Aug 20 inli 9-1/2" Hole / L/WD / RST to 2900m 11:00 hrs 11:00 hrs 11:00 hrs 12:30 Thu 03 Aug CBU 11:00 hrs 12:00 hrs				Make up BHA	04:30 Tue 01 Aug
11.00 hrs 11.0			10.00 hrs	RIH to TD	12:30 Tue 01 Aug
18:30 Thu 03 Aug 19:10			33.00 hrs	Drill 9-1/2" Hole / LWD / RST to 2900m	22:30 Tue 01 Aug
18:30 Fri 04 Aug 50:30 Sun 06 Aug 50:30 Sun 06 Aug 50:30 Sun 06 Aug 70:30 Sun 07 Aug 70:30 Sun 07 Su			11.00 hrs	CBU	07:30 Thu 03 Aug
19.33 Sun 06 Aug CBU 25.00 hrs 25.			24.00 hrs	Round Trip	18:30 Thu 03 Aug
16:30 Sun 06 Aug			33.00 hrs	Drill 9-1/2" Hole / LWD / RST to 3600m	18:30 Fri 04 Aug
16:30 Mon 07 Aug Drill 9-1/2" Hole / LWD / RST to 4600m S0.00 hrs NOTE: This is the minimum of planned to be drilled			12.00 hrs	CBU	03:30 Sun 06 Aug
18:30 Med 07 Aug 28 20.00 hrs 20.0			25.00 hrs	Round Trip	15:30 Sun 06 Aug
12:30 Thu 10 Aug R/U to Run 7" Liner 4.00 hrs R/U to Run 7" Liner 4.00 hrs R/U to Run 7" Liner 4.00 hrs 15:30 Fri 11 Aug Run 7" Liner on DP (include 10%" casing scraper in running string) 15:00 hrs 15:00 hrs 16:00 hrs 16	oth	NOTE: This is the minimum deptl planned to be drilled	50.00 hrs	Drill 9-1/2" Hole / LWD / RST to 4600m	16:30 Mon 07 Aug
12:30 Fri 11 Aug Run 7" Liner 4.00 hrs 12:30 Fri 11 Aug Run 7" Liner 15:00 hrs 15:00 hrs 15:00 hrs 16:00 hrs			18.00 hrs	CBU	18:30 Wed 09 Aug
12:30 Fri 11 Aug Run 7" Liner 15:00 hrs 15:00 hrs 18:30 Sat 12 Aug 12:30 Sut 13 Aug 12:30 Sut			20.00 hrs	POOH	12:30 Thu 10 Aug
18:30 Sat 12 Aug Run 7" Liner on DP (include 10%" casing scraper in running string) 15.00 hrs			4.00 hrs	R/U to Run 7" Liner	08:30 Fri 11 Aug
18:30 Sat 12 Aug Set Lnr / Displace to brine 8.00 hrs 02:30 Sun 13 Aug POOH with DP, scrape casing at approx 2160m 10.00 hrs 12:30 Sun 13 Aug Tub g handling equip, make up 1300m of 3%" TCP guns and 900m of 4½" 38.00 hrs 02:30 Tue 15 Aug RIH TCP guns on 3½" & 5" DP to approx 4500m (top shot at ~2300m), fire guns and icr bottoms up 18.00 hrs 20:30 Tue 15 Aug POOH and lay out spent guns 24.00 hrs 20:30 Wed 16 Aug POOH and lay out spent guns 24.00 hrs 20:30 Tue 17 Aug Run Baker SC-1R Packer with FBIV on DP, sting into top of 7" Liner, set packer and start prox 2160m, test casing and prox 2160m packer, spot HIVIs pill & POOH dillpipe 9.00 hrs 17:30 Thu 17 Aug Release setting tool from packer, spot HIVIs pill & POOH dillpipe 9.00 hrs 05:30 St 19 Aug Run, land and test SST 24.00 hrs 05:30 St 19 Aug Run, land and test BOPs 24.00 hrs 21:30 Thu 17 Aug Run Scraper & Well Patroller, with SABS and Riser Brush, sting in & install plug 12.00 hrs 15.00 hrs 09:30 Sun 20 Aug Circulate 10%" casing to 10.4 ppg filter			15.00 hrs	Run 7" Liner	12:30 Fri 11 Aug
18:30 Sat 12 Aug Set Lnr / Displace to brine 02:30 Sun 13 Aug POOH with DP, scrape casing at approx 2160m 10.00 hrs 12:30 Sun 13 Aug Ru tog handling equip, make up 1300m of 3%" TCP guns and 900m of 4½" 38.00 hrs 17CP guns, arm firing head and install circulating valve 17CP guns, arm firing head and install circulating valve 18:400 hrs and circ bottoms up 20:30 Tue 15 Aug POOH and lay out spent guns 20:30 Tue 15 Aug POOH and lay out spent guns 18:00 hrs and circ bottoms up 20:30 Tue 15 Aug POOH and lay out spent guns 18:00 hrs 20:30 Tue 16 Aug Aug POOH and lay out spent guns 18:00 hrs 21:30 Thu 17 Aug Release setting tool from packer, spot HIVIs pill & POOH drillpipe 9.00 hrs 21:30 Thu 17 Aug Release and recover BOPs to surface 8.00 hrs 21:30 Thu 17 Aug Run, land and test SST 24:00 hrs 21:30 Thu 17 Aug Run, land and test SST 24:00 hrs 21:30 Thu 17 Aug Run, land and test SST 24:00 hrs 21:30 Sat 19 Aug Run, land and test BOPs 21:30 Sat 19 Aug Run, land and test BOPs 21:30 Sat 19 Aug Run Scraper & Well Patroller, with SABS and Riser Brush, sting in & install plug 12:00 hrs 21:30 Sun 20 Aug 21:30 Sun 20 Aug 22:30 Mon 21 Aug 22:30 Mon 21 Aug 24:30 Mon 21 Aug 25:30 Mon 21 Aug 26:30 Mon 21 Aug 26:30 Mon 21 Aug 26:30 Mon 21 Aug 27:30 Mon 21 Aug 27:30 Mon 21 Aug 28:30 Mon 21 Aug 29:30 Mon 21 Aug 30 Mon 22 Aug 30 Mon 22 Aug 30 Rill spear on DP, retrieve packer plug / debris sub, POOH sideways 12:00 hrs 30 Tue 22 Aug 30 Rill spear on DP, retrieve packer sind 5½" completion (~35 jts / assys) 15:00 hrs 30 Tue 22 Aug 30 Rill spear on DP, retrieve packer sind 5½" completion (~35 jts / assys) 15:00 hrs 30 Tue 24 Aug 30 Mon 24 Aug			15.00 hrs	Run 7" Liner on DP (include 10¾" casing scraper in running string)	03:30 Sat 12 Aug
12:30 Sun 13 Aug POOH with DP, scrape casing at approx 2160m 10.00 hrs					18:30 Sat 12 Aug
12:30 Sun 13 Aug R/u to gh andling equip, make up 1300m of 33/s* TCP guns and 900m of 41/s* TCP guns, arm firing head and install circulating valve RIH TCP guns on 31/s* 8.5" DP to approx 4500m (top shot at ~2300m), fire guns and circ bottoms up POH and lay out spent guns 20:30 Tue 15 Aug POH and lay out spent guns RIH TCP guns on 31/s* 8.5" DP to approx 4500m (top shot at ~2300m), fire guns and circ bottoms up POH and lay out spent guns 24:00 hrs 12:00 hrs 12:30 Thu 17 Aug Release setting tool from packer, spot HiVis pill & POH drillpipe 17:30 Thu 17 Aug Release setting tool from packer, spot HiVis pill & POH drillpipe 18:00 hrs 19:30 Fri 18 Aug Run, land and test SST 24:00 hrs 10:30 Sat 19 Aug Run, Land and test BOPs 16:00 hrs 21:30 Sat 19 Aug Run Scraper & Well Patroller, with SABS and Riser Brush, sting in & install plug / debris sub in SC-1R packer 09:30 Sun 20 Aug Run Scraper & Well Patroller, with SABS to clean up riser, BOP and wellhead, POH 15:30 Mon 21 Aug Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 103/s* casing from top of liner to 1700mMDRT 21:30 Tue 22 Aug Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 103/s* casing from top of liner to 1700mMDRT 21:30 Tue 22 Aug Rig up tubing handling equipment 20:00 hrs 10:30 Tue 22 Aug Rig up tubing handling equipment 20:00 hrs 10:30 Tue 22 Aug Rig up tubing handling equipment 20:00 hrs 10:30 Thu 24 Aug M/u SSSV, run remaining 7" completion (~6 jis / assys, 3 x C-L Flatpacks) Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & 9.00 hrs 10:30 Thu 24 Aug M/u SSSV, run remaining 7" completion (~6 jis / assys, 3 x C-L Flatpacks) 10:00 hrs 10:30 Thu 24 Aug M/u SSSV, run remaining 7" completion (~6 jis / assys, 3 x C-L Flatpacks) 10:00 hrs 10:30 Thu 24 Aug M/u SSSV, run remaining 7" completion (~6 jis / assys, 3 x C-L Flatpacks)			10.00 hrs		02:30 Sun 13 Aug
TCP guns, arm firring head and install circulating valve RIH TCP guns on 37% 8 5" DP to approx 4500m (top shot at ~2300m), fire guns and circ bottoms up 20:30 Tue 15 Aug POOH and lay out spent guns Run Baker SC-1R Packer with FBIV on DP, sting into top of 7" Liner, set packer at approx 2160m, test casing Run Baker SC-1R Packer with FBIV on DP, sting into top of 7" Liner, set packer at approx 2160m, test casing Release setting tool from packer, spot HiVis pill & POOH drillpipe 9.00 hrs 17:30 Thu 17 Aug Release and recover BOPs to surface 9:30 Fri 18 Aug Run, land and test SST 24.00 hrs 21:30 Sat 19 Aug Run, land and test BOPs 21:30 Sat 19 Aug Circulate 10¾" casing to 10.4 ppg filtered inhibited brine and then spot HEC pill across perf interval. 09:30 Mon 21 Aug Rip up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10¾" casing from top of liner to 1700mMDRT 21:30 Tue 22 Aug RiH appear on DP, retrieve packer plug / debris sub, POOH sideways 12:30 Tue 22 Aug Rig up tubing handling equipment 20:30 Wed 23 Aug Run 7" completion (~145 jts / assys, 2 x C-L Flatpacks) Make up and run Tubing Hanger and THRT on 7" landing string (inc) SSTT & 9.00 hrs 16:30 Thu 24 Aug Make up and run Tubing Hanger and THRT on 7" landing string (inc) SSTT & 9.00 hrs 16:30 Thu 24 Aug Make up and run Tubing Hanger and THRT on 7" landing string (inc) SSTT & 9.00 hrs 16:30 Thu 24 Aug Make up and run Tubing Hanger and THRT on 7" landing string (inc) SSTT & 9.00 hrs 16:30 Thu 24 Aug Make up and run Tubing Hanger and THRT on 7" landing string (inc) SSTT & 9.00 hrs		Start Completion			
02:30 Tue 15 Aug 20:30 Tue 15 Aug 20:30 Tue 15 Aug 20:30 Tue 15 Aug 20:30 Wed 16 Aug Run Baker SC-1R Packer with FBIV on DP, sting into top of 7" Liner, set packer at approx 2160m, test casing 08:30 Thu 17 Aug Release setting tool from packer, spot HiVis pill & POOH drillpipe 9.00 hrs 17:30 Thu 17 Aug RiH & set 10'4" Bridge Plug below wellhead, POOH 4.00 hrs 21:30 Thu 17 Aug Release and recover BOPs to surface 8.00 hrs 05:30 Sat 19 Aug Run, land and test SST 24.00 hrs 09:30 Sat 19 Aug Circulate 10'x" casing to 10.4 ppg filtered inhibited brine and then spot HEC pill 09:30 Sun 20 Aug Rock HCC pill, open SABS to clean up riser, BOP and wellhead, POOH 15:30 Mon 21 Aug Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10'%" casing from top of liner to 1700mMDRT 21:30 Mon 21 Aug Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10'%" casing for 10:00 hrs 19:30 Tue 22 Aug Ril H spear on DP, retrieve packer plug / debris sub, POOH sideways 19:30 Tue 22 Aug Ril H spear on DP, retrieve packer plug / debris sub, POOH sideways 12:30 Wed 23 Aug Run DHC Equip / 2 packers and 5'x" completion (~35 jts / assys, 2 x C-L Flatpacks) Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & 9.00 hrs SLV)		• • • •	, , , , , , , , , , , , , , , , , , , ,		12:30 Sun 13 Aug
20:30 Tue 15 Aug 20:30 Tue 15 Aug POOH and lay out spent guns 20:30 Wed 16 Aug Run Baker SC-1R Packer with FBIV on DP, sting into top of 7" Liner, set packer at approx 2160m, test casing 8:30 Thu 17 Aug Release setting tool from packer, spot HiVis pill & POOH drillpipe 9:00 hrs 17:30 Thu 17 Aug Release setting tool from packer, spot HiVis pill & POOH drillpipe 9:00 hrs 21:30 Thu 17 Aug Release and recover BOPs to surface 8:00 hrs 05:30 Fri 18 Aug Run, land and test SST 24:00 hrs 05:30 Sat 19 Aug Run, land and test BOPs Run Scraper & Well Patroller, with SABS and Riser Brush, sting in & install plug 12:30 Sat 19 Aug Circulate 10½" casing to 10.4 ppg filtered inhibited brine and then spot HEC pill across perf interval. 00:30 Mon 21 Aug Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10¾" casing from top of liner to 1700mMDRT 21:30 Mon 21 Aug Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10¾" casing 6:00 hrs 19:30 Tue 22 Aug Rig up tubing handling equipment 21:30 Tue 22 Aug Rig up tubing handling equipment 21:30 Wed 23 Aug Run IDHC Equip / 2 packers and 5½" completion (~35 jts / assys) 12:30 Thu 24 Aug Miu SSSV, run remaining 7" completion (~6 jts / assys, 3 x C-L Flatpacks) Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & SUN SSLV)			18.00 hrs		
20:30 Tue 15 Aug 20:30 Wed 16 Aug Run Baker SC-1R Packer with FBIV on DP, sting into top of 7" Liner, set packer at approx 2160m, test casing 08:30 Thu 17 Aug Release setting tool from packer, spot HiVis pill & POOH drillpipe 9.00 hrs 17:30 Thu 17 Aug RIH & set 10%" Bridge Plug below wellhead, POOH 4.00 hrs 21:30 Thu 17 Aug Release and recover BOPs to surface 8.00 hrs 05:30 Fri 18 Aug Run, land and test SST 24.00 hrs 05:30 Fri 18 Aug Run, land and test BOPs Run, land and test BOPs 16:00 hrs 21:30 Sat 19 Aug Run Scraper & Well Patroller, with SABS and Riser Brush, sting in & install plug / debris sub in SC-1R packer 09:30 Sun 20 Aug 09:30 Sun 20 Aug POOH to above HEC pill, open SABS to clean up riser, BOP and wellhead, POOH Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10%" casing from top of liner to 1700mMDRT 21:30 Mon 21 Aug RIH and perforate 400 sands overbalanced (2 runs), POOH & r/d 07:30 Tue 22 Aug RIH spear on DP, retrieve packer plug / debris sub, POOH sideways 12:30 Tue 22 Aug Run IDHC Equip / 2 packers and 5%" completion (~35 jts / assys) 12:30 Tue 22 Aug Run SSSV, run remaining 7" completion (~6 jts / assys, 3 x C-L Flatpacks) SLV) 24:00 hrs S4:00 hrs 12:00 hrs 12:30 Thu 24 Aug Rid spear on DP, retrieve packer and THRT on 7" landing string (incl SSTT & SSLV)					02:30 Tue 15 Aug
20:30 Wed 16 Aug Run Baker SC-1R Packer with FBIV on DP, sting into top of 7" Liner, set packer at approx 2160m, test casing Release setting tool from packer, spot HIVis pill & POOH drillpipe 9.00 hrs 17:30 Thu 17 Aug Release setting tool from packer, spot HIVis pill & POOH drillpipe 9.00 hrs RIH & set 10½" Bridge Plug below wellhead, POOH 4.00 hrs 21:30 Thu 17 Aug Release and recover BOPs to surface 8.00 hrs 95:30 Fri 18 Aug Run, land and test SST 24.00 hrs 05:30 Sat 19 Aug Run, land and test BOPs Run Scraper & Well Patroller, with SABS and Riser Brush, sting in & install plug / debris sub in SC-1R packer Circulate 10½" casing to 10.4 ppg filtered inhibited brine and then spot HEC pill across perf interval. 00:30 Mon 21 Aug POOH to above HEC pill, open SABS to clean up riser, BOP and wellhead, POOH 15:30 Mon 21 Aug Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10¾" casing from top of liner to 1700mMDRT 21:30 Mon 21 Aug RIH and perforate 400 sands overbalanced (2 runs), POOH & r/d 07:30 Tue 22 Aug RIH spear on DP, retrieve packer plug / debris sub, POOH sideways 19:30 Tue 22 Aug Run IDHC Equip / 2 packers and 5½" completion (~35 jts / assys) 15:00 hrs 12:30 Thu 24 Aug MIV SSSV, run remaining 7" completion (~6 jts / assys, 3 x C-L Flatpacks) SSLV)			24 00 hrs		20:30 Tue 15 Aug
20:30 Wed 16 Aug at approx 2160m, test casing 08:30 Thu 17 Aug Release setting tool from packer, spot HiVis pill & POOH drillpipe 9.00 hrs 17:30 Thu 17 Aug Release and recover BOPs to surface 8.00 hrs 05:30 Fri 18 Aug Run, land and test SST 24:00 hrs 05:30 Sat 19 Aug Run, land and test BOPs 21:30 Sat 19 Aug Run Scraper & Well Patroller, with SABS and Riser Brush, sting in & install plug debris sub in SC-1R packer 09:30 Sun 20 Aug 00:30 Mon 21 Aug POOH to above HEC pill, open SABS to clean up riser, BOP and wellhead, POOH Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10¾" casing from top of liner to 1700mMDRT 21:30 Mon 21 Aug Ril and perforate 400 sands overbalanced (2 runs), POOH & r/d 19:30 Tue 22 Aug Ril gup tubing handling equipment 21:30 Tue 22 Aug Run IDHC Equip / 2 packers and 5½" completion (~35 jts / assys) 16:30 Thu 24 Aug Missing Aug Missing Release setting tool from packer, spot HiVis pill & POOH hrs 9.00 hrs 9.00 hrs 9.00 hrs 15.00 hrs 15.00 hrs 15.00 hrs 15.00 hrs 12.00 hrs					
08:30 Thu 17 AugRelease setting tool from packer, spot HiVis pill & POOH drillpipe9.00 hrs17:30 Thu 17 AugRIH & set 10%" Bridge Plug below wellhead, POOH4.00 hrs21:30 Thu 17 AugRelease and recover BOPs to surface8.00 hrs05:30 Fri 18 AugRun, land and test SST24.00 hrs05:30 Sat 19 AugRun, land and test BOPs16.00 hrs21:30 Sat 19 AugRun Scraper & Well Patroller, with SABS and Riser Brush, sting in & install plug / debris sub in SC-1R packer12.00 hrs09:30 Sun 20 AugCirculate 10%" casing to 10.4 ppg filtered inhibited brine and then spot HEC pill across perf interval.15.00 hrs00:30 Mon 21 AugPOOH to above HEC pill, open SABS to clean up riser, BOP and wellhead, POOH15.00 hrs15:30 Mon 21 AugRig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10%" casing from top of liner to 1700mMDRT6.00 hrs21:30 Mon 21 AugRiH and perforate 400 sands overbalanced (2 runs), POOH & r/d10.00 hrs07:30 Tue 22 AugRig up tubing handling equipment2.00 hrs21:30 Tue 22 AugRig up tubing handling equipment2.00 hrs21:30 Tue 22 AugRun IDHC Equip / 2 packers and 5½" completion (~35 jts / assys)15.00 hrs12:30 Thu 24 AugMulv SSSV, run remaining 7" completion (~6 jts / assys, 3 x C-L Flatpacks)4.00 hrs16:30 Thu 24 AugMake up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & SSLV)9.00 hrs			72.00 III 3		20:30 Wed 16 Aug
17:30 Thu 17 Aug RIH & set 10¾" Bridge Plug below wellhead, POOH 21:30 Thu 17 Aug Release and recover BOPs to surface 8.00 hrs 05:30 Fri 18 Aug Run, land and test SST 24.00 hrs 16:30 Sat 19 Aug Run, land and test BOPs Run Scraper & Well Patroller, with SABS and Riser Brush, sting in & install plug debris sub in SC-1R packer Circulate 10¾" casing to 10.4 ppg filtered inhibited brine and then spot HEC pill across perf interval. POOH to above HEC pill, open SABS to clean up riser, BOP and wellhead, pOOH 15:30 Mon 21 Aug RIH and perforate 400 sands overbalanced (2 runs), POOH & r/d 19:30 Tue 22 Aug Run IDHC Equip / 2 packers and 5½" completion (~35 jts / assys) 16:30 Thu 24 Aug Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & 9.00 hrs SSLV) 16:30 Thu 24 Aug Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & 9.00 hrs S4.00 hrs S4.00 hrs S4.00 hrs S4.00 hrs S4.00 hrs S4.00 hrs S6.00 hrs			9 00 hrs		08:30 Thu 17 Aug
21:30 Thu 17 Aug Release and recover BOPs to surface 8.00 hrs 95:30 Fri 18 Aug Run, land and test SST 94:00 hrs 16:00 hrs 21:30 Sat 19 Aug Run Scraper & Well Patroller, with SABS and Riser Brush, sting in & install plug / debris sub in SC-1R packer Circulate 10½" casing to 10.4 ppg filtered inhibited brine and then spot HEC pill across perf interval. POOH to above HEC pill, open SABS to clean up riser, BOP and wellhead, POOH 15:30 Mon 21 Aug Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10¾" casing from top of liner to 1700mMDRT 21:30 Mon 21 Aug RIH and perforate 400 sands overbalanced (2 runs), POOH & r/d 19:30 Tue 22 Aug Run IDHC Equip / 2 packers and 5½" completion (~35 jts / assys) 12:30 Thu 24 Aug Mus SSV, run remaining 7" completion (~6 jts / assys, 3 x C-L Flatpacks) Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & 9.00 hrs 24.00 hrs 16:30 Thu 24 Aug Mus SSLV)					
05:30 Fri 18 Aug Run, land and test SST 24.00 hrs 05:30 Sat 19 Aug Run, land and test BOPs 16.00 hrs 21:30 Sat 19 Aug Run Scraper & Well Patroller, with SABS and Riser Brush, sting in & install plug / debris sub in SC-1R packer Circulate 10%" casing to 10.4 ppg filtered inhibited brine and then spot HEC pill across perf interval. 00:30 Mon 21 Aug POOH to above HEC pill, open SABS to clean up riser, BOP and wellhead, POOH 15:30 Mon 21 Aug Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10%" casing from top of liner to 1700mMDRT 21:30 Mon 21 Aug RiH and perforate 400 sands overbalanced (2 runs), POOH & r/d 10.00 hrs 07:30 Tue 22 Aug Rig up tubing handling equipment 2.00 hrs 19:30 Tue 22 Aug Run Tie Call Aug Run 7" completion (~145 jts / assys, 2 x C-L Flatpacks) 24.00 hrs 12:30 Thu 24 Aug Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & SSLV)					
05:30 Sat 19 Aug Run, land and test BOPs Run Scraper & Well Patroller, with SABS and Riser Brush, sting in & install plug / debris sub in SC-1R packer 09:30 Sun 20 Aug Circulate 10¾" casing to 10.4 ppg filtered inhibited brine and then spot HEC pill across perf interval. POOH to above HEC pill, open SABS to clean up riser, BOP and wellhead, POOH Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10¾" casing from top of liner to 1700mMDRT 21:30 Mon 21 Aug Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10¾" casing from top of liner to 1700mMDRT 21:30 Mon 21 Aug RIH and perforate 400 sands overbalanced (2 runs), POOH & r/d 07:30 Tue 22 Aug Rig up tubing handling equipment 2.00 hrs 21:30 Tue 22 Aug Run IDHC Equip / 2 packers and 5½" completion (~35 jts / assys) 15:00 hrs 12:30 Wed 23 Aug Run 7" completion (~145 jts / assys, 2 x C-L Flatpacks) Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & 9.00 hrs SSLV)					
21:30 Sat 19 Aug Run Scraper & Well Patroller, with SABS and Riser Brush, sting in & install plug / debris sub in SC-1R packer O9:30 Sun 20 Aug Circulate 10¾" casing to 10.4 ppg filtered inhibited brine and then spot HEC pill across perf interval. POOH to above HEC pill, open SABS to clean up riser, BOP and wellhead, POOH 15:30 Mon 21 Aug Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10¾" casing from top of liner to 1700mMDRT 21:30 Mon 21 Aug RIH and perforate 400 sands overbalanced (2 runs), POOH & r/d 19:30 Tue 22 Aug RIH spear on DP, retrieve packer plug / debris sub, POOH sideways 19:30 Tue 22 Aug Rig up tubing handling equipment 2:30 Tue 22 Aug Run IDHC Equip / 2 packers and 5½" completion (~35 jts / assys) 12:30 Wed 23 Aug Run 7" completion (~145 jts / assys, 2 x C-L Flatpacks) 16:30 Thu 24 Aug Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & 9.00 hrs SSLV)				· ·	
/ debris sub in SC-1R packer 09:30 Sun 20 Aug Circulate 10¾" casing to 10.4 ppg filtered inhibited brine and then spot HEC pill across perf interval. 00:30 Mon 21 Aug POOH to above HEC pill, open SABS to clean up riser, BOP and wellhead, POOH 15:30 Mon 21 Aug Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10¾" casing from top of liner to 1700mMDRT 21:30 Mon 21 Aug RIH and perforate 400 sands overbalanced (2 runs), POOH & r/d 19:30 Tue 22 Aug RIH spear on DP, retrieve packer plug / debris sub, POOH sideways 19:30 Tue 22 Aug Rig up tubing handling equipment 2.00 hrs 21:30 Tue 22 Aug Run IDHC Equip / 2 packers and 5½" completion (~35 jts / assys) 12:30 Wed 23 Aug Run 7" completion (~145 jts / assys, 2 x C-L Flatpacks) 16:30 Thu 24 Aug M/u SSSV, run remaining 7" completion (~6 jts / assys, 3 x C-L Flatpacks) Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & 9.00 hrs SSLV)				,	
O9:30 Sun 20 Aug Circulate 10¾" casing to 10.4 ppg filtered inhibited brine and then spot HEC pill across perf interval. O0:30 Mon 21 Aug POOH to above HEC pill, open SABS to clean up riser, BOP and wellhead, POOH Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10¾" casing from top of liner to 1700mMDRT 21:30 Mon 21 Aug RIH and perforate 400 sands overbalanced (2 runs), POOH & r/d 19:30 Tue 22 Aug RIH spear on DP, retrieve packer plug / debris sub, POOH sideways 19:30 Tue 22 Aug Rig up tubing handling equipment 21:30 Tue 22 Aug Run IDHC Equip / 2 packers and 5½" completion (~35 jts / assys) 12:30 Thu 24 Aug M/u SSSV, run remaining 7" completion (~6 jts / assys, 3 x C-L Flatpacks) Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & 9.00 hrs			12.00 1113		21:30 Sat 19 Aug
POOH to above HEC pill, open SABS to clean up riser, BOP and wellhead, POOH 15:30 Mon 21 Aug Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10¾" casing from top of liner to 1700mMDRT 21:30 Mon 21 Aug RIH and perforate 400 sands overbalanced (2 runs), POOH & r/d 10:00 hrs RIH spear on DP, retrieve packer plug / debris sub, POOH sideways 12:00 hrs Rig up tubing handling equipment 21:30 Tue 22 Aug Run IDHC Equip / 2 packers and 5½" completion (~35 jts / assys) 12:30 Wed 23 Aug Run T" completion (~145 jts / assys, 2 x C-L Flatpacks) 12:30 Thu 24 Aug M/u SSSV, run remaining 7" completion (~6 jts / assys, 3 x C-L Flatpacks) Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & 9.00 hrs SSLV)			15.00 hrs	Circulate 10¾" casing to 10.4 ppg filtered inhibited brine and then spot HEC pill	09:30 Sun 20 Aug
15:30 Mon 21 Aug Rig up Schlumberger electricline, run CBL/VDL/GR/CCL Log inside 10¾" casing from top of liner to 1700mMDRT 21:30 Mon 21 Aug RIH and perforate 400 sands overbalanced (2 runs), POOH & r/d 10:00 hrs 19:30 Tue 22 Aug RIH spear on DP, retrieve packer plug / debris sub, POOH sideways 19:30 Tue 22 Aug Rig up tubing handling equipment 21:30 Tue 22 Aug Run IDHC Equip / 2 packers and 5½" completion (~35 jts / assys) 12:30 Wed 23 Aug Run 7" completion (~145 jts / assys, 2 x C-L Flatpacks) 12:30 Thu 24 Aug M/u SSSV, run remaining 7" completion (~6 jts / assys, 3 x C-L Flatpacks) 16:30 Thu 24 Aug Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & 9.00 hrs			15.00 hrs	POOH to above HEC pill, open SABS to clean up riser, BOP and wellhead,	00:30 Mon 21 Aug
from top of liner to 1700mMDRT 21:30 Mon 21 Aug RIH and perforate 400 sands overbalanced (2 runs), POOH & r/d 07:30 Tue 22 Aug RIH spear on DP, retrieve packer plug / debris sub, POOH sideways 12:00 hrs 19:30 Tue 22 Aug Rig up tubing handling equipment 2.00 hrs 21:30 Tue 22 Aug Run IDHC Equip / 2 packers and 5½" completion (~35 jts / assys) 12:30 Wed 23 Aug Run 7" completion (~145 jts / assys, 2 x C-L Flatpacks) 12:30 Thu 24 Aug M/u SSSV, run remaining 7" completion (~6 jts / assys, 3 x C-L Flatpacks) 16:30 Thu 24 Aug Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & 9.00 hrs			6.00 hrs		
21:30 Mon 21 Aug RIH and perforate 400 sands overbalanced (2 runs), POOH & r/d 10:00 hrs RIH spear on DP, retrieve packer plug / debris sub, POOH sideways 12:00 hrs 19:30 Tue 22 Aug Rig up tubing handling equipment 2:00 hrs 21:30 Tue 22 Aug Run 1DHC Equip / 2 packers and 5½" completion (~35 jts / assys) 15:00 hrs Run 7" completion (~145 jts / assys, 2 x C-L Flatpacks) 12:30 Thu 24 Aug M/u SSSV, run remaining 7" completion (~6 jts / assys, 3 x C-L Flatpacks) 16:30 Thu 24 Aug Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & SSLV)					15:30 Mon 21 Aug
07:30 Tue 22 AugRIH spear on DP, retrieve packer plug / debris sub, POOH sideways12.00 hrs19:30 Tue 22 AugRig up tubing handling equipment2.00 hrs21:30 Tue 22 AugRun IDHC Equip / 2 packers and 5½" completion (~35 jts / assys)15.00 hrs12:30 Wed 23 AugRun 7" completion (~145 jts / assys, 2 x C-L Flatpacks)24.00 hrs12:30 Thu 24 AugM/u SSSV, run remaining 7" completion (~6 jts / assys, 3 x C-L Flatpacks)4.00 hrs16:30 Thu 24 AugMake up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & SSLV)9.00 hrs			10.00 hrs		21:30 Mon 21 Aug
19:30 Tue 22 Aug Rig up tubing handling equipment 2.00 hrs 21:30 Tue 22 Aug Run IDHC Equip / 2 packers and 5½" completion (~35 jts / assys) 15.00 hrs 12:30 Wed 23 Aug Run 7" completion (~145 jts / assys, 2 x C-L Flatpacks) 24.00 hrs 12:30 Thu 24 Aug M/u SSSV, run remaining 7" completion (~6 jts / assys, 3 x C-L Flatpacks) 4.00 hrs 16:30 Thu 24 Aug Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & SSLV)					
21:30 Tue 22 Aug Run IDHC Equip / 2 packers and 5½" completion (~35 jts / assys) 12:30 Wed 23 Aug Run 7" completion (~145 jts / assys, 2 x C-L Flatpacks) 12:30 Thu 24 Aug M/u SSSV, run remaining 7" completion (~6 jts / assys, 3 x C-L Flatpacks) 16:30 Thu 24 Aug Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & SSLV)					
12:30 Wed 23 Aug Run 7" completion (~145 jts / assys, 2 x C-L Flatpacks) 12:30 Thu 24 Aug M/u SSSV, run remaining 7" completion (~6 jts / assys, 3 x C-L Flatpacks) 16:30 Thu 24 Aug Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & SSLV) 24.00 hrs 4.00 hrs 9.00 hrs					
12:30 Thu 24 Aug M/u SSSV, run remaining 7" completion (~6 jts / assys, 3 x C-L Flatpacks) 16:30 Thu 24 Aug M/u SSSV, run remaining 7" completion (~6 jts / assys, 3 x C-L Flatpacks) 4.00 hrs 9.00 hrs SSLV)					
16:30 Thu 24 Aug Make up and run Tubing Hanger and THRT on 7" landing string (incl SSTT & SSLV) 9.00 hrs					
SSLV)					
					16:30 Thu 24 Aug
			6.00 hrs	,	01:30 Fri 25 Aua
07:30 Fri 25 Aug Lock, overpull, close BOPs and test hanger.					
Pressure up tubing string against FRIV and set bottom (AHC) packer, pressure 2.00 brs					
09:30 Fri 25 Aug test tubing.					09:30 Fri 25 Aug
11:30 Fri 25 Aug Open ICV and displace tubing string to diesel. 4.00 hrs			4.00 hrs		11:30 Fri 25 Aug
Pressure up on control lines to set top (HE1) packer and close upper ICV 2.00 hrs					
15:30 Fri 25 Aug pressure test tubing again.					15:30 Fri 25 Aug
Pressure test annulus, top packer and hanger seals. Prepare to flow well, conduct safety meeting. 4.00 hrs			4.00 hrs		17:30 Fri 25 Aug
21:30 Fri 25 Aug Open ICV and flow well to clean up Upper Group (400 sands). 3.00 hrs			3.00 hrs		21:30 Fri 25 Aua
Flow Upper Group through separator (at 4 different rates) take PVT, bulk & 12,00 hrs					
00:30 Sat 26 Aug assay samples.			2.001110		00:30 Sat 26 Aug
12:30 Sat 26 Aug SIW at surface and perform build-up test on Upper Group. 12.00 hrs			12.00 hrs		12:30 Sat 26 Aug
00:30 Sun 27 Aug Close upper ICV and perform in-flow test to ensure closed OK. 2.00 hrs					
02:30 Sun 27 Aug Lubricate diesel into well, pressure cycle top and bottom FBIVs open. 8.00 hrs					
10:30 Sun 27 Aug Flow well to clean up Lower Group (300/200/100 sands). 9.00 hrs					
• 1				T	