Well : BASKER FFD

NOTE: Other sheets use this START DATE & TIME & POB Information in their setup

Starting POB : 81
Max POB on rig : 100
Start Date & Time : Sat 25-Feb-06 8:00
Forecast End Time : 24/03/2006 18:00:00 PM

Start Time	Description	Target	Actual	Comments	Done ?
08:00 Sat 25 Feb	Move rig to manifold position	6.00 hrs	2.50 hrs		☺
10:30 Sat 25 Feb	Run anchors and position rig over Basker 5	12.00 hrs	14.50 hrs		☺
01:00 Sun 26 Feb	Pick up BHA and Cmt / 30" RT stands	4.00 hrs	8.50 hrs		☺
09:30 Sun 26 Feb	Drill 36" hole	3.00 hrs	2.50 hrs		☺
12:00 Sun 26 Feb	Run and cement 30" casing	12.00 hrs	19.00 hrs	PGB angle problems	☺
07:00 Mon 27 Feb	Position rig over Basker 4	2.00 hrs	1.00 hrs		☺
08:00 Mon 27 Feb	Attempt to Drill 36" hole excess hole angle	3.00 hrs	7.00 hrs		☺
15:00 Mon 27 Feb	POOH change BHA P/U MWD RIH	3.00 hrs	9.00 hrs		☺
00:00 Tue 28 Feb	MWD Fail POOH changeout MWD RIH	3.00 hrs	3.00 hrs		☺
03:00 Tue 28 Feb	Drill 36" hole	3.00 hrs	3.50 hrs		☺
06:30 Tue 28 Feb	Run and cement 30" casing	12.00 hrs	13.00 hrs		☺
19:30 Tue 28 Feb	Move to B-5 and perform top up cement job on conductor	0.00 hrs	6.50 hrs		☺
02:00 Wed 01 Mar	Position rig over Basker 3	2.00 hrs	2.50 hrs		
04:30 Wed 01 Mar	Drill 36" hole	3.00 hrs			☺
07:30 Wed 01 Mar	Run and cement 30" casing	12.00 hrs			
19:30 Wed 01 Mar	M/U 171/2" BHA and drill shoe track	8.00 hrs			
03:30 Thu 02 Mar	Drill 17 1/2" Hole	36.00 hrs			
15:30 Fri 03 Mar	Run 13 3/8" casing and cement same	18.00 hrs			
09:30 Sat 04 Mar	Position rig over Basker 4	2.00 hrs			
11:30 Sat 04 Mar	M/U 17 1/2" BHA and drill shoe track	8.00 hrs			
19:30 Sat 04 Mar	Drill 17 1/2" Hole	36.00 hrs			
07:30 Mon 06 Mar	Run 13 3/8" casing and cement same	18.00 hrs			
01:30 Tue 07 Mar	Position rig over Basker 5	2.00 hrs			✂☼☜☞✐
03:30 Tue 07 Mar	M/U 17 1/2" BHA and drill shoe track	8.00 hrs			
11:30 Tue 07 Mar	Drill 17 1/2" Hole	36.00 hrs			
23:30 Wed 08 Mar	Run 13 3/8" casing and cement same	18.00 hrs			
17:30 Thu 09 Mar	Run BOP and riser	15.00 hrs			
08:30 Fri 10 Mar	M/U 12 1/4" BHA and drill out casing. Perform LOT	10.00 hrs			
18:30 Fri 10 Mar	Drill 12 1/4" Hole	216.00 hrs			
18:30 Sun 19 Mar	Condition Hole. POOH. Rig up and make 3 wireline evaluation runs	48.00 hrs			
18:30 Tue 21 Mar	RIH. Condition Hole. Run and cement 9 5/8" casing.	48.00 hrs			
18:30 Thu 23 Mar	Suspend well. Release and pull BOP/riser	22.00 hrs			
16:30 Fri 24 Mar	Position rig over Basker Manifold location	2.00 hrs			
18:30 Fri 24 Mar	Basker 2 re-entry to remove gauges	84.00 hrs			✂☼☜☞✐
06:30 Tue 28 Mar	Drill 42" hole and set 36" pile for Basker Manifold	36.00 hrs			
18:30 Wed 29 Mar	Position rig over Basker 4	2.00 hrs			
20:30 Wed 29 Mar	Run BOP and riser	15.00 hrs			
11:30 Thu 30 Mar	M/U 12 1/4" BHA and drill out casing. Perform LOT	10.00 hrs			
21:30 Thu 30 Mar	Drill 12 1/4" Hole	216.00 hrs			
21:30 Sat 08 Apr	Condition Hole. POOH. Rig up and make 3 wireline evaluation runs	48.00 hrs			
21:30 Mon 10 Apr	RIH. Condition Hole. Run and cement 9 5/8" casing.	48.00 hrs			
21:30 Wed 12 Apr	Suspend well. Release and lift BOPs	8.00 hrs			
05:30 Thu 13 Apr	Position rig over Basker 3	2.00 hrs			
07:30 Thu 13 Apr	Land BOP and riser and test	8.00 hrs			
15:30 Thu 13 Apr	M/U 12 1/4" BHA and drill out casing. Perform LOT	10.00 hrs			
01:30 Fri 14 Apr	Drill 12 1/4" Hole	216.00 hrs			✂☼☜☞✐
01:30 Sun 23 Apr	Condition Hole. POOH. Rig up and make 3 wireline evaluation runs	48.00 hrs			✂☼☜☞✐
01:30 Tue 25 Apr	RIH. Condition Hole. Run and cement 9 5/8" casing	48.00 hrs			✂☼☜☞✐
01:30 Thu 27 Apr	Start Completion on Basker-3				✂☼☜☞✐
					☺
					✂☼☜☞✐
					☺