

20 Jul 2008 From: B Openshaw/R Rossouw

To: R Oliver

# DRILLING MORNING REPORT # 32 Longtom-4

Well Data									
Country	Australia	MDBRT	2600.0m	Cur. Hole Size	13.500in	AFE Cost	AUD\$81,987,600		
Field	Longtom	TVDBRT	2351.2m	Last Casing OD	10.750in	AFE No.	LSRDV01/6		
Drill Co.	Seadrill	Progress	0.0m	Shoe TVDBRT	2337.6m	Daily Cost	AUD\$650,000		
Rig	West Triton	Days from spud	29.94	Shoe MDBRT	2590.8m	m Cum Cost AUD\$35,241,			
Wtr Dpth (LAT)	55.968m	Days on well	31.63	FIT/LOT:	/ 1.64sg	1.64sg			
RT-ASL (LAT)	41.062m	Planned TD MD	5822.000m	Current Op @ 0600	Connecting up CTU on Texas deck.				
RT-ML	97.030m	Planned TD TVDRT	2702.000m	Planned Op	Install Claxton clamp, take tension on riser with CTU and install and nipple up BOP.				

### Summary of Period 0000 to 2400 Hrs

Lowered SST on to 18.75in wellhead, set down 30klbs weight, activate H4 and take 50k o/pull test. Pressure tested VX ring to 5000psi, changed out IWOCS from SST to TRT and recovered TRT. Set down TRT on deck. Lowered Texas deck, picked up H4 connector and ran same with 22in riser.

HSE Summary				
Events	Num. Events	Days Since	Descr.	Remarks
Abandon Drill		0 Days	Held at10.35 hours.	Rig alarms activated.
Drills	1	5 Days	Spill Drill	A containment drill was held on a failed equalisation valve between the sand trap tanks.
Dropped Object		7 Days	Broken bolt on Link Tilt bracket.	When the link Tilt was retracted, the uneven piston movement caused the clamp bolt (on the Bail Arm) to break. The end of the bolt (10mm X 50mm) fell to the rig floor. Clamp remained coupled to the Bail Arm.
First Aid Case	1	3 Days	Floorman had his hand struck by tong jaw.	At 01h40 on 17 July, Floorman was changing the Tong Jaw. He lifted the jaw and was pulling the locating pin out when the open tong jaw swung round and struck his left wrist. He reported to medic immediately. Medic examined man and Ice applied to back of hand. Returned to work shortly after.
Incident	To Days  Elevator contact with Monkeyboard.  When racking back the Casing Running was short. As a result, the elevators may corner of the Monkey Board, causing sl		When racking back the Casing Running Tool, the stand was short. As a result, the elevators made contact with the corner of the Monkey Board, causing slight damage to support beam	
PTW issued	11	0 Days		Permit to work issued for the day.
Safety Meeting	2	0 Days	Weekly Safety Meetings with crews.	Weekly safety meeting held at 0045 Sunday morning and 1300 on Saturday .
STOP Card	46	0 Days		Stop cards submitted for the day.

FORMATION	
Name	Тор
Kipper Shale	1755.00m
Admiral Formation.	2186.00m
500 Sands	2316.00m
400 Sands	2494.00m
300 Sands	2564.00m

### Operations For Period 0000 Hrs to 2400 Hrs on 20 Jul 2008

Phse	Cls (RC)	Ор	From	То	Hrs	Depth	Activity Description
P26	Р	G10	0000	0100	1.00	2600.0m	Skidded rig for final alignment and landed SST on 18.75in wellhead. Slacked off 30k lbs on to wellhead and activated H4 with 3000psi pressure. Observed H4 indicator move to fully closed position. Took 50k lbs o/pull to confirm connection. Confirmed SST orientation of 270 deg using ROV.
P26	Р	P2	0100	0200	1.00	2600.0m	Pressure tested VX ring to 5000psi for 15min.
P26	Р	G10	0200	0230	0.50	2600.0m	Set down 50klbs weight and unlatched TRT.
P26	Р	G10	0230	0400	1.50	2600.0m	ROV disconnected IWOCS stabbing plate from SST and connected same to TRT for recovery.
P26	Р	G10	0400	0430	0.50	2600.0m	ROV performed survey around SST to confirm no snags for recovery of TRT. Held umbilical away from SST at one potential snagging point.



Phse	Cls (RC)	Ор	From	То	Hrs	Depth	Activity Description				
P26	Р	G10	0430	0530	1.00	2600.0m	Pulled TRT above SST, skidded rig forward to allow for recovery of umbilical. POOH TRT.				
P26	Р	G10	0530	0700	1.50	2600.0m	Skidded rig out to allow space for lifting of TRT above hull into moonpool.				
P26	Р	G1	0700	0730	0.50	2600.0m	Removed scaffold work platform.				
P26	Р	G1	0730	1000	2.50	2600.0m	Skidded cantilever in and rig floor transversely to align TRT with skid frame, set down on frame and disconnected DP from TRT.				
P26	Р	G1	1000	1200	2.00	2600.0m	Lowered Texas deck down.				
P26	Р	G9	1200	1500	3.00	2600.0m	Held PJSM, picked up H4 connector and skidded rig out to align with Texas deck slot.				
P22	Р	G1	1500	1530	0.50	2600.0m	Installed stairway and handrails on Texas deck.				
P22	Р	G1	1530	1700	1.50	2600.0m	Installed C-plate on Texas deck and landed H4 on C-plate. Rigged down H4 handling equipment and rigged up W/ford 22in equipment.				
P22	Р	G10	1700	1830	1.50	2600.0m	Held PJSM and ran 22in riser to Texas deck.				
P22	Р	G10	1830	2000	1.50	2600.0m	Made up DQ RBC connector on to top of H4 and torqued up locking dogs.				
P22	Р	G10	2000	2100	1.00	2600.0m	Connected 2 core umbilical jumpers on H4 connector and strapped same to riser. Function tested umbilical controls.				
P22	TP (TP)	G10	2100	2200	1.00	2600.0m	Unable to remove riser protectors from riser joints (protectors damaged). Removed protectors by cutting same.				
P22	Р	G9	2200	2400	2.00	2600.0m	Continued running 22in riser joints while strapping umbilical to riser.				

Operations For Period 0000 Hrs to 0600 Hrs on 21 Jul 2008

Phse	Cls (RC)	Ор	From	То	Hrs	Depth	Activity Description
P22	Р	G9	0000	0100	1.00	2600.0m	Continued running 22in riser.
P22	P	G9	0100	0400	3.00	2600.0m	Changed out handling equipment, picked up DP stand with DQ clutch type r/tool and made up same to wellhead joint. Stroked H4 to open position. Lowered riser and manipulated positioning with tuggers and ROV to enable latching on to SST with H4 connector. Set down 10klbs weight on SST and activated H4 with 1500psi activating pressure. Observed H4 indicator showing fully locked position. Lock in activating pressure at surface. Performed 50k o/pull test on H4 OK.
P22	Р	P1	0400	0500	1.00	2600.0m	Filled riser with sea water and fluorescene dye from cementing unit. Attempted pressure test to 500psi on H4 and riser - DQ clutch type r/tool leaking. Abandon test.
P22	Р	G1	0500	0600	1.00	2600.0m	Lowered CTU into position and nippled up same. Offline: Connected service hoses and wedged skid points on cantilever.

# **Operations For Period Hrs to Hrs on**

Phase Data to 2400hrs, 20 Jul 2008						
Phase	Phase Hrs	Start On	Finish On	Cum Hrs	Cum Days	Max Depth
Mob/Demob(P1)	35	19 Jun 2008	20 Jun 2008	35.00	1.458	0.0m
Conductor Hole(P2)	10.5	20 Jun 2008	21 Jun 2008	45.50	1.896	132.8m
Conductor Casing(P3)	19.5	21 Jun 2008	22 Jun 2008	65.00	2.708	132.8m
Surface Hole(P4)	54	22 Jun 2008	24 Jun 2008	119.00	4.958	755.0m
Surface Casing(P5)	40	24 Jun 2008	25 Jun 2008	159.00	6.625	755.0m
BOPs/Risers(P6)	62.5	26 Jun 2008	28 Jun 2008	221.50	9.229	755.0m
Other work scope(P28)	1	28 Jun 2008	28 Jun 2008	222.50	9.271	755.0m
Production Hole (1)(P11)	286	28 Jun 2008	10 Jul 2008	508.50	21.188	2600.0m
Production Casing(1)(P13)	188.5	10 Jul 2008	18 Jul 2008	697.00	29.042	2600.0m
Completion/Recompletion(P22)	47	18 Jul 2008	20 Jul 2008	744.00	31.000	2600.0m
Sub-sea Work(P26)	15	20 Jul 2008	20 Jul 2008	759.00	31.625	2600.0m

Sub-sea Work(1 20)		15 20 Jul 2006	20 Jul 2000	739.00	31.023	2000.0111
General Comments						
00:00 TO 24:00 Hrs ON 20 Jul 200	8					
Operational Comments	Adjustments to rotary RT above LAT = 41.06 RT above MSL/AHD 4	o calculations;				
Operational Comments	impacting operational  2) Number 4 main ger	ment Concerns ead has operating problems, efficiency. New hydraulic pur erator down. Exciter and gen nas leaking valves, pressure r	np on order - deli erator sent asho	very mid Septeml re.	oer.	rst. This is



General Comments	
	4) Link tilt clamps slipping on bails - need to rectify this issue.
	5) Bail retaining plates on top drive bent, increasing time to change out bails by 1/2 hour. Require new retaining plates.
	6) No spare UpperTop Drive IBOP or parts on board for Upper IBOP.
	7) #3 Main Engine down - waiting on parts.
	8) Emergency generator fuel tank requires modification to drain line (no communication with tank through drain line).
Operational Comments	Jar hours = 99.5 hours.
Operational Comments	Claxton clamp slip segment successfully retieved with ROV.
Operational Comments	Flowline connector orientation on SST is 270deg.
Operational Comments	All rams, except shear rams, tested on BOP.

SBM Data				Cost Today AUD\$ 2089							
Mud Type:	ACCOLADE	HTHP-Temp:	120C°	Ex.Lime:		Solids(%vol):	22%	Viscosity	130sec/qt		
Oil Type:	ACCOLADE	HTHP:	500psi	Salinity:	264070mg/l	H2O:	24%	YP PV	31lb/100ft <sup>2</sup> 32cp		
	BASE	HTHP-FL:	3.0cc/30min	Elec.Stab.:	490mV	Oil(%):	52%	O/W Ratio:	68.4		
Sample-From:	Pit 6	HTHP-cake:	1/32nd"			Sand:	.25	Gels 10s Gels 10m	13 17		
Time:	21:00	CaCl mud:	30.09			LGS:	13%	Fann 003	11		
Weight:	12.10sg	CaCl WP:				Oil On Cut:		Fann 006	13		
Temp:	20C°	Caci WF.				Oil Oil Cut.		Fann 100	34		
								Fann 200			
Comment								Fann 300	63		
								Fann 600	95		

Bulk Stocks					
Name	Unit	In	Used	Adjust	Balance
Drill Water	MT	0	8	0	216.0
Rig Fuel	m3	0	5	0	278.0
POTABLE WATER	MT	12	27	0	296.0
Cement class \'G\'	MT	0	0	0	71.0
Bentonite	MT	0	0	0	45.0
Barite	MT	0	0	0	204.0
SOBM	m3	58	0	0	86.0

Pυ	ımps																
Pu	Pump Data - Last 24 Hrs							Slow Pump Data									
No.	Туре	Liner (in)	MW (sg)	Eff (%)	SPM (SPM)	SPP (psi)	Flow (gpm)	Depth (m)	SPM1 (SPM)				SPM3 (SPM)		Flow3 (gpm)		
1	National 14 P-220	6.50	1.40	97				2590.0	30	300	176	40	370	234	50	500	293
2	National 14 P-220	6.50	1.40	97					20		120	30		176	40		234
3	National 14 P-220	6.50	1.40	97					20		120	30		176	40		234

Casing			
OD	LOT / FIT	Csg Shoe (MD/TVD)	Cementing
30 "	/	128.80m / 128.80m	168bbl class G at 15.9ppg, 200% excess.
16 "	/	750.03m / 750.03m	Lead 516 bbls "G" class at 12.5ppg. Tail 229 bbls "G" class at 15.80 ppg
10 3/4"	/	2590.78m / 2337.57m	200bbl class "G" at 15.8ppg, TOC at 1900m

Personnel On Board					
Company	Pax				
ADA	7				
Seadrill	13				
Seadrill Services.	43				



Personnel On Board	
Catering	9
Halliburton	2
Baker Hughes Inteq	4
Halliburton	2
Tamboritha	6
Q Tech	1
Tasman Oil Tools	2
Cameron	2
Weatherford	4
Reach	1
Dril-Quip	1
ROV-UIS	1
Baker Atlas	3
Schlumberger	4
Total	105

Mud Volumes, Mud Losses and Shale Shaker Data  Engineer: Brian Auckram/James Munford							
Available	3057.3bbl	Losses	0.0bbl	Equipment	Description	Mesh Size	Comments
Active	220.0bbl	Downhole					
Mixing		Surf+ Equip	0.0bbl				
Hole	1699.3bbl	Dumped					
Slug Reserve	1138.0bbl	De-Gasser De-Sander					
Kill		De-Silter Centrifuge					

# Marine

Weather on 20 Jul 2008

Visibility	Wind Speed	Wind Dir.	Pressure	Air Temp.	Wave Height	Wave Dir.	Wave Period	
10.0nm	7kn	270.0deg	1001.0mbar	11C°	1.0m	270.0deg	2s	
Rig Dir.	Ris. Tension	VDL	Swell Height	Swell Dir.	Swell Period	Weather Comments		
24.1deg		2631.00klb	2.1m	160.0deg	6s	Wave and swell heights		
Comments						are estimates.		

Vessel Name	Arrived (Date/Time)	Departed (Date/Time)	Status		Bulks		
Pacific Battler	12.15hrs 13-07-08		En route to Geelong	Item	Unit	Used	Quantity
				Rig Fuel	m3		602.6
				Potable Water	Mt		418
				Drill Water	Mt		300
				CEMENT G	Mt		0
				Barite	Mt		0
				Bentonite	Mt		0
				Base Oil	m3		0
				Brine	m3		0
Pacific Valkyrie			At rig	ltam	I Imia		
raciiic vaikyiie			Attig	Item	Unit	Used	Quantity
racilic valkylle			Attig			Used	
racinc valkyne			Actig	Rig Fuel Potable Water	m3	Used	Quantity 349.3 332
raciiic vaikyrie			Actig	Rig Fuel	m3	Used	349.3
raciiic valkyrie			Acing	Rig Fuel Potable Water	m3 Mt	Used	349.3 332
racine valkyne			Attig	Rig Fuel Potable Water Drill Water	m3 Mt m3	Used	349.3 332 718
racine valkyne			Attig	Rig Fuel Potable Water Drill Water CEMENT G	m3 Mt m3 Mt	Used	349.3 332 718 0
racine valkyne			Attig	Rig Fuel Potable Water Drill Water CEMENT G Barite	m3 Mt m3 Mt	Used	349.3 332 718 0 105
raciiic vaikyne			Attig	Rig Fuel Potable Water Drill Water CEMENT G Barite Bentonite	m3 Mt m3 Mt Mt	Used	349.3 332 718 0 105 34.8