

To <operational.reports@dpi.vic.gov.au>, <bkunjan@awexp.com.au>, <bjwood@awexp.com.au>, "Buick, Glen" <Glen.Buick@santos.com>,

CC

bcc

Subject Netherby 1DW1 15:00hrs update 5/08/08

Depth: 1944m Progress: 0m

Operation: Washing and reaming into the hole. Current bit depth 1890m.

Hole condition has improved. Minimal "pressured" cavings at the shakers. Returns are soft

dispersive claystone.

OPERATIONS SINCE 06:00 to 15:30 hrs EST:

Continue back reaming and pumping out of hole from 1420m to 1135m. Pump a hi-vis sweep and circulate the hole clean. Run in hole, take weight at 1337m. Wash and ream into the hole. Bit depth 1890m at 15:30hrs.

ANTICIPATED OPERATIONS:

Run in washing and reaming to total depth. Circulate hole clean. Pull out of hole and run 244mm (9 5/8") / 273mm (10%") casing

Michael FX Giuliano

Senior Staff Operations Geologist Exploration & New Ventures

Santos

Santos Centre, 60 Flinders Street Adelaide SA 5000 **Australia**

Tel: +618 8116 7673 **Mob:** +61 418 821 275

Email: michael.giuliano@santos.com

Santos

Santos Ltd A.B.N. 80 007 550 923

Disclaimer: The information contained in this email is intended only for the use of the person(s) to whom it is addressed and may be confidential or contain privileged information.

If you are not the intended recipient you are hereby notified that any perusal, use, distribution, copying or disclosure is strictly prohibited.

If you have received this email in error please immediately advise us by return email and delete the email without making a copy.

Please consider the environment before printing this email

