



PE905642

Fairly tight section

Gas kicks & cut. 9960-9970  
Fluor. in cut. 9965-9975

Core 14 (not recovered) TD 10,007

9481 (2 1/2") Lower limit of logs

9326 FLUORESCENCE

PLUG 1 8956-8961

PLUG 2 8245-8250

7390 U.C.R.E.T. 7630 WATER GAS

Insufficient pay section north

PLUG 3 6790-6800

Exceedingly resistive (see tests)

LOGS TO 5414

4910 L.V.F.M. 5110 OIL 5153 WATER 5500

(Longer of coming of water in lower test) longer & gas in upper test

4404 Top of fish (2/9/66) fish stuck at 5325

2251 (13 3/4") 2472 Top of fish (5/9/66)

760' (20")

354' (30")

188'

31' RT

Vertical scale 1" = 500'  
Horizontal scale 0.4" = 10'  
" 1" = 25'