


$K_f = \text{Apparent formation reliability}$
 $= R \times 10^5$
 $\frac{W}{D} \times N$

$d' \text{ exp} = \log \left[\frac{K}{60N} \right]$
 $\log \left[\frac{12W}{10^5 D} \right]$



CLEVERPRINT PAPER CO. C32 10 X 10 DIVISIONS PER INCH 400 X1000 DIVISIONS

CLEVERPRINT CHARTS

PRINTED IN U.S.A. ON CLEVERPRINT TECHNICAL PAPER NO. 1012

DEPT. NAT. RES & ENV



PE603321