

## Line Log

Line Name: GNX05-06-01-003  
 Start time: 09/02/2005 20:01:45

Client: NEXUS  
 Contract: Vic/P39

Shotpoint	Log Time	Message
1000	09/02/2005 20:01:47	LINE START - GNX05-06-01-003 shot 1000 time 2-9-2005 20:1:45.444806
	09/02/2005 20:01:47	SOL String pressures 1:2041.3 PSI 2:1999.3 PSI 3:1995.5 PSI
	09/02/2005 20:01:47	Volume source 1 3040 cu in (ideal volume 3040) 100.0%
1001	09/02/2005 20:01:52	Start of line GNX05-06-01-003 shot 1001
1254	09/02/2005 20:37:01	String_2 Cluster_2 Gun_3 (300 cu in) fired 1.1 mS early.
1255	09/02/2005 20:37:09	String_2 Cluster_2 Gun_3 (300 cu in) fired 1.2 mS early.
1335	09/02/2005 20:48:07	String_2 Cluster_2 Gun_3 (300 cu in) fired 1.1 mS early.
1816	09/02/2005 21:52:25	String_2 Cluster_2 Gun_3 (300 cu in) fired 1.1 mS early.
	09/02/2005 22:19:38	Missed Shot(s). Last S.P. 2026 this shot 0 (expected increment/decrement 1)
	09/02/2005 22:19:41	LOST SHOT - TCU did not detect T0 - Failed to see fire signal before timeout (predict settings wrong ?)
	09/02/2005 22:19:48	END OF LINE GNX05-06-01-003 shot 0 time 2-9-2005 22:19:42.035000
	09/02/2005 22:19:48	EOL String pressures 1:2085.3 PSI 2:2040.7 PSI 3:2040.2 PSI
	09/02/2005 22:19:48	EOL Volume source 1 3040 cu in.
		Total shots on line = 1028 Shots with one or more errors 3 (0.3%)
		Shots with bad timing 3 (0.3%)