

Line Log

Line Name: GNX05-13-01-006
 Start time: 10/02/2005 08:33:26

Client: NEXUS
 Contract: Vic/P39

Shotpoint	Log Time	Message
1002	10/02/2005 08:33:33	SOL Depth transducers - String_2 DT_3 DEAD
1001	10/02/2005 08:33:33	LINE START - GNX05-13-01-006 shot 1001 time 2-10-2005 8:33:26.453813
1002	10/02/2005 08:33:34	SOL String pressures 1:1987.3 PSI 2:1945.8 PSI 3:1947.5 PSI
	10/02/2005 08:33:34	Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	10/02/2005 08:33:34	stats - updateShotpoint: Duplicate shotpoint or stats slow, one shotpoint dropped
	10/02/2005 08:33:34	stats - fireSQL: ... ERROR: Cannot insert a duplicate key into unique index shotpoint.key
	10/02/2005 08:33:34	stats - fireSQL: insert into shotpoint (number, line_id, stime)values(1002, 8830, '2-10-2005 8:33:33.664813')
1057	10/02/2005 08:40:14	tcucom - main: Lost sync with TCU - didn't see CR when expected - %GD096 looking for 102 got 17 plus 'G'
1086	10/02/2005 08:43:45	tcucom - process_tcu_message: Common clock was 1000 milli seconds fast
1088	10/02/2005 08:43:58	tcucom - process_tcu_message: Common clock was 990 milli seconds slow
1977	10/02/2005 10:36:35	String_1 Cluster_1 Gun_2 (250 cu in) fired 1.1 mS late.
1979	10/02/2005 10:36:50	String_1 Cluster_1 Gun_2 (250 cu in) fired 1.2 mS late.
	10/02/2005 10:44:22	Missed Shot(s). Last S.P. 2034 this shot 0 (expected increment/decrement 1)
	10/02/2005 10:44:25	LOST SHOT - TCU did not detect T0 - Failed to see fire signal before timeout (predict settings wrong ?)
	10/02/2005 10:44:32	EOL Depth transducers - String_2 DT_3 DEAD
	10/02/2005 10:44:32	END OF LINE GNX05-13-01-006 shot 0 time 2-10-2005 10:44:25.935000
	10/02/2005 10:44:32	EOL String pressures 1:2087.3 PSI 2:2042.3 PSI 3:2041.0 PSI
	10/02/2005 10:44:32	EOL Volume source 1 3040 cu in.
		Total shots on line = 1034 Shots with one or more errors 1 (0.1%)
		Shots with bad timing 1 (0.1%)