



# Improvement / Incident Details



Generated on Monday, 17 August 2009

## Incident

**Ref No:** SI-112

**Status:** Pending

**Type:** Site Improvement

## Identification Details

**Name:** Symeoy, Anthony

**ID No:** **External:**

**Location:** Mt Franklin

**Source:** **Grid Ref:**

**Reported:** 27 May 2009 **Job No:**

## Incident Date/Time/Location

**Date:** 27 May 2009 **Time:**

**Address:**

**Location:** Mt Franklin

**State/Ctry:** VIC **Region:** Australia

**Site Type:** Rig 6-TLD

## Incident / Improvement Details

**Category:** Rig Improvement **Level:** 1 **Severity:** Minor

**Summary:** Corrective action IIR for Audit AUD-1035

**Description:** Audit: AUD-1035  
Type: Rig Inspection (TLD Rig 6)  
Category: Rig Inspection  
Program: Inspection/Testing Program

**Injury:**  **Near Miss:**  **Improvement:**  **Environmental:**  **Manual Handling:**  **Asset Damage:**

**Contractor:**

**Employees:**

**Contractors:**

**Division:** Titeline Drilling

**Function:**

**Task:**

**Contract No:**

**Risk Assess:**

**Audit No:** AUD-1035

**Costing:**

**Plan. Project:**

**Proj. Phase:**

**Project Task:**

**Assigned To:** Arthur, Justin

**Delegate:**

**Assigned Date:** 28 May 2009

**Action By Date:**

**Close-off Date:**

## Investigation Details

**Cause Cat:**

**Equip No:**

**Plant No:**

**Cause Desc:**

**Likelihood:**

**Conseq:**

**Re-occur Rat:**

**Exposure:**

**Persons:**

**Risk No:**

**Report Doc:**

**Survey Answers:**

**Survey Rating:**

**Answering Employee:**