



Improvement / Incident Details



Generated on Monday, 17 August 2009

Incident

Ref No: IJ-139

Status: Closed

Type: Injury/Illness

Identification Details

Name: Creasy, Matthew

ID No: 439

External:

Location: Unspecified

Source:

Grid Ref:

Reported: 01 Aug 2009

Job No:

Incident Date/Time/Location

Date: 31 Jul 2009

Time: 03:00 PM

Address:

Location: Addington

State/Ctry: VIC

Region: Australia

Site Type: Rig 6-TLD

Incident / Improvement Details

Category: Fall

Level: 1

Severity: Insignificant

Summary: Fell off Rod rack while attempting to remove Core from Lifter

Description: MC was standing on the rod rack attempting to remove core from lifter when he fell off the rack landing on his right shoulder. AC did not see the incident but did see MC on the ground. AC checked MC who said he was ok

Injury: **Near Miss:** **Improvement:** **Environmental:** **Manual Handling:** **Asset Damage:**

Contractor:

Employees: Creasy, Matthew - Cartledge, Andrew

Contractors:

Division: Titeline Drilling

Function:

Task:

Contract No:

Risk Assess:

Audit No:

Costing:

Plan. Project:

Proj. Phase:

Project Task:

Assigned To: Arthur, Justin

Delegate:

Assigned Date: 03 Aug 2009

Action By Date: 03 Aug 2009

Close-off Date: 04 Aug 2009

Investigation Details

Cause Cat:

Equip No:

Plant No:

Cause Desc:

Likelihood:

Conseq:

Re-occur Rat:

Exposure:

Persons:

Risk No:

Report Doc:

Survey Answers:

Survey Rating:

Answering Employee: