# **EAPL WellWork Daily Operations Report**

# Daily Operations: 24 HRS to 6/03/2007 06:00

Well Name Snapper A19

Rig Name Company

> Imperial Snubbing Services Rig 22

Job Subcategory

Plug and Abandon the A-19

Report Start Date/Time Report End Date/Time Report Number 5/03/2007 06:00 6/03/2007 06:00

Currency Total Original AFE Amount Total AFE Supplement Amount

AFE or Job Number 40000470 - Rig Move. AUD 1,516,470 1,804,000

Days Ahead/Behind **Cumulative Cost Daily Cost Total** 

92,827

165,824

### Management Summary

Load boat Far Scandia. Clear rig floor and work window. Clean and service equipment. Load work baskets and prepare back loads. Clear and clean pipe deck. Rig down pipe work around tanks and machinery deck. Remove drill lines, gas buster, choke manifold, east wind walls and rig up erection lines. Rig down monkey board.

#### Activity at Report Time

Scope down mast

### **Next Activity**

Continue to scope down mast

# Daily Operations: 24 HRS to 6/03/2007 06:00

Well Name

Bream B10

Rig Name Company

> Wireline Halliburton / Schlumberger

Job Subcategory Plan

Replace Xmas tree Report Start Date/Time Report End Date/Time **Report Number** 

5/03/2007 06:00 6/03/2007 06:00 15

AFE or Job Number Currency Total Original AFE Amount Total AFE Supplement Amount

46000482 AUD 200,000 Days Ahead/Behind **Daily Cost Total Cumulative Cost** 

18,367 225,438

# **Management Summary**

Crews arrived at BMB, circ 20 bbls to ensure well clean. Set dummy gas lift valve. Pressure op on tbg and test to 1000 psi for 15 minutes. Wait on weather

### Activity at Report Time

**SDFN** 

### **Next Activity**

Complete gas lift change out set TWC and replace tree

### Daily Operations: 24 HRS to 5/03/2007 14:00

Well Name Bream B5

Rig Name Company

Job Subcategory

Kill Surface Annulus Report Start Date/Time Report End Date/Time Report Number

5/03/2007 12:00 5/03/2007 14:00 AFE or Job Number Currency **Total Original AFE Amount Total AFE Supplement Amount** 

46000485 AUD 50,000

Days Ahead/Behind **Daily Cost Total Cumulative Cost** 

# **Management Summary**

Press test SA to 2000 kpa for 30 minutes. Test solid. Advised to wait on orders

**Activity at Report Time** 

# **Next Activity**

Wait on orders

**ExxonMobil Use Only** Page 1 of 1 Printed on 6/03/2007