EAPL WellWork & Drilling Daily Operations Report

Daily Operations: 24 HRS	to 8/06/2007 05:00	
Well Name		
Fortescue A6a		
Rig Name	Company	
Rig 175	International Sea Drilling LTD (ISDL)	
Primary Job Type	Plan	
Drilling and Completion	D&C	
Target Measured Depth (mKB)	Target Depth (TVD) (mKB)	
3,911.88		
AFE or Job Number	Total Original AFE Amount	Total AFE Supplement Amount
L0501H005	8,931,209	
Daily Cost Total	Cumulative Cost	Currency
255,433	672,521	AUD
Report Start Date/Time	Report End Date/Time	Report Number
7/06/2007 05:00	8/06/2007 05:00	3

Management Summary

Continue to change top pipe rams to 7 5/8" solids and middle pipe rams to 4" solids. Close and re-torque bonnet bolts.Crane install safety clamps on air lift sea water line. Skid BOP's under rotary table and secure same. Rig to and change out wash pipe on top drive. Conduct rig service.Clear rig floor of excess equipment. Make up 5 1/2" test assy and engage same. Rig up high pressure lines. Howco pressure test BOP's, choke and stand pipe manifold to 300/3000 psi for 5 mins. Break down test assy. Howco test blind rams. Change out saver sub on TDS. Make up 4" test assy. Howco test BOP's 4", 300/3000 psi for 5 mins. Break down 4" test assy. Clear rig floor. Nipple down BOP from test stump. Nipple up to riser. Install bell nipple. Install flow lines, drains, and bell nipple seals. Tie down BOP. Continue to torque up riser connections. Service Far Scandia.

Activity at Report Time Nipple up BOP's. L/out 4" DP.

Next Activity L/out DP. Mill 7" EZSV.

Daily Operations: 24 HRS to 8/06/2007 05:00

Well Name Halibut A7a Rig Name Company Rig 453 International Sea Drilling LTD (ISDL) Primary Job Type Plan Mobilization Only Target Measured Depth (mKB) Target Depth (TVD) (mKB) AFE or Job Number Total Original AFE Amount **Total AFE Supplement Amount** L0501H213 6,430,000 Daily Cost Total **Cumulative Cost** Currency 101,362 2,926,604 AUD Report Start Date/Time **Report End Date/Time Report Number** 7/06/2007 05:00 8/06/2007 05:00 3 Management Summary Held PTSM's & conduct hazard hunts. Continue to rig down 3rd party equipment - Howco, Geoservices, HES, and Maersk. Prepare mud pumps and BOP's for rig down. Pack up equipment and prepare for backload off rig. Work vessel Far Scandia @ HLA for backload of equipment to BBMT. Activity at Report Time Continue with rig down operations. Next Activity

Continue with rig down operations. Backloading equipment and chemicals.

EAPL WellWork & Drilling Daily Operations Report

		y operatione report	
Daily Operations: 24 HRS	to 8/06/2007 06:00		
Well Name			
Snapper A7			
Rig Name	Company		
Rig 22	Imperial Snubbing Services		
Primary Job Type	Plan		
Plug and Abandonment Only	Plug and Abandon the A-7		
Target Measured Depth (mKB)	Target Depth (TVD) (mKB)		
2,303.00			
AFE or Job Number	Total Original AFE Amount	Total AFE Supplement Amount	
40000484	1,915,000	1,085,000	
Daily Cost Total	Cumulative Cost	Currency	
83,167	2,773,157	AUD	
Report Start Date/Time	Report End Date/Time	Report Number	
7/06/2007 06:00	8/06/2007 06:00	35	
Management Summary			
		utter. Pick up and run tapped mill clean out BHA. Wash in hole from	
	ill cutting/cement debris in returns. Pump 10 bbls Hivi	s pills at intervals.	
Activity at Report Time			
Circulating hole clean.			
Next Activity			
Run casing cutter and make three 2	24m cuts.		
Daily Operations: 24 HRS	to 8/06/2007 06:00		
Well Name			
Cobia A18B			
Rig Name	Company		
Wireline	Halliburton / Schlumberger		
Primary Job Type	Plan		
Workover PI	Gyro & PLT/DEFT survey, possible isolation		
Target Measured Depth (mKB)	Target Depth (TVD) (mKB)		
1,713.40			
AFE or Job Number	Total Original AFE Amount	Total AFE Supplement Amount	
46000487	315,000		
Daily Cost Total	Cumulative Cost	Currency	
25,704	193,931	AUD	
Report Start Date/Time	Report End Date/Time	Report Number	
7/06/2007 06:00	8/06/2007 06:00	10	
Management Summary			
	ey. Wait on Production to shut well in. Set MPBT @ 25	568mts mdkb. Dump water on MPBT@2568mts mdkb. Dump cement	
on MPBT@2568mts mdkb.			
Activity at Report Time			
Rigging down BOPs etc.			
Next Activity			
Complete rig down, hand well to Pr			