



SONY 

Esso Australia DLIS
MARLIN A5

Cased Hole - SBHP-GR (1845-1960m)

 PE012589

Encom ID: 1965785 Copy of: 4

SONY 

Esso Australia DLIS
MARLIN A16

Cased Hole - SBHP-GR (1792-1905m)

 PE012590

Encom ID: 1965786 Copy of: 5

DLIS/IMG Proj: 10155
 Cartridge ID: 1965785

Client:
MARLIN A5
 25/03/99

1 SBHP Surface check before survey
 2 SBHP-GR Correlation Log (1845-1960m)
 3-8 SBHP Static Logs (1900.5, 1910.2, 1989.7, 1969.2, 1732.2 & 3324m)
 9 SBHP Surface check after survey

Client: ESSO Australia 1965785
MARLIN A5

Encom Technology Pty. Limited
 Level 2, 118 Alfred St. Milsons Pt NSW 2061
 PO Box 422 Milsons Pt. NSW 1565
 ph: (61 2) 9957 4117 fax: (61 2) 9922 6141
 email: encom@encom.com.au

DLIS/IMG Proj: 10155
 Cartridge ID: 1965786

Client:
MARLIN A16
 28/03/99

1 SBHP Surface check after survey
 2-7 SBHP Static Logs (1593.7, 1720.8, 1842.7, 1960.2, 1877.7 and 1895m)
 8 SBHP-GR Correlation (1792-1905m)
 9 SBHP Surface check before survey

Client: ESSO Australia 1965786
MARLIN A16

Encom Technology Pty. Limited
 Level 2, 118 Alfred St. Milsons Pt NSW 2061
 PO Box 422 Milsons Pt. NSW 1565
 ph: (61 2) 9957 4117 fax: (61 2) 9922 6141
 email: encom@encom.com.au