



Total Depth 8846'

DRY and ABANDONED
12 JANUARY 1961.

- Packer failed to hold.
- Packer failed to hold.
- Packer set too low.
- Open 90m. Val blow dec to nil at 7m. No SI. Rec 750 GCMW. Sal 1050ppm.
- Open 157m. Val blow ceased 25m. Rec 480'W. Sal 900-1000ppm.
- Fish consisting of 5DCs and bit 8306'-8154'.
- Packer failed to hold.
- Packer failed to hold.
- Packer failed to hold.
- Open 158m. Gd blow ceased 13m. 6.18 33m. Swb 40 bbl GCW - SI 60m. Rec 380 GCMW. Sal 850ppm. Rec 580 GCMW. Sal 8300ppm.
- Open 210m. SI blow throughout. Swb 14 bbl GCW. SI 30m. Rec 185 bbl GCW. Sal 8300ppm.
- SI 38m. Fr blow decreasing. Sal 8300ppm.
- Open 83m. Gd blow decreasing. Swb 25 bbl. M. Rec 5445 dirty W. Sal 900-920ppm.
- Open 380m. SI blow ceasing 30m. Swb 1 bbl & Rec 1810'W. Sal 8230ppm.
- Packer failed to hold.
- Open 99m. SI blow decreased in 60m. SI 18m. Swb 60 bbl GCW. Sal 794ppm. Rec 30 bbl GCW. Sal 1800ppm.
- Packer failed to hold.
- Open 86m. Gd blow dead in 60m. SI 25m. Swb 40 bbl GCW. Sal 8000ppm. Rec 0.48 @ 63°F.
- Open 78m. Gd blow decreased to sl. SI 42m. Rec 180 GCMW. Sal 7500 GCMW. Rec 0.48 @ 63°F.
- Tool did not open.
- Open 120m. Gd blow decreasing. SI 34m. Swb 60 bbl GCW. Sal 8000ppm. Rec 31 bbl GCW. Sal 8000ppm. Rec 0.48 @ 63°F.
- Tool did not open.
- Open 87m. Fr blow decreasing. SI 38m. Rec 6370 GCMW. Sal 7900-7800ppm. Rec 0.48 @ 63°F.
- Open 68m. SI blow decreasing. SI 42m. Rec 270 M. 80' GCMW. 3070' GCW. 180' GCW. Sal 8300ppm.
- Packers failed to hold.
- Open 18m. Packer unsheathed. Rec 3300' DM.