



SANTOS Ltd

Galloway-1

FTWD PRESSURE TEST #1 (2125.91 mMDRT / 1177.06 mTVDRT)

<i>FTWD Pressure</i>			<i>FTWD Remarks</i>
<i>0</i>	<i>3000</i>		
<i>lbs / in2 abs</i>			
		17:08:00	SEND DO FT COMMAND
		17:09:00	
		17:10:00	
		17:11:00	
		17:12:00	START PRETEST #1
		17:13:00	DO DRAWDOWN #1
		17:14:00	
		17:15:00	
		17:16:00	
		17:17:00	





17:18:00

17:19:00

17:20:00

17:21:00

17:22:00

17:23:00

SEND DO DRAWDOWN

**END BUILDUP;
PSTOP 1676.00 PSIA**

END PRETEST

FTWD Pressure

0 3000

lbs / in2 abs

FTWD Remarks

SANTOS Ltd

Galloway-1


FTWD PRESSURE TEST #2 (2126.93 mMDRT / 1178.04 mTVDRT)

FTWD Pressure

0 3000

lbs / in2 abs

FTWD Remarks



17:37:00


17:38:00

17:39:00

17:40:00

SEND DO FT COMMAND

START PRETEST #2



17:41:00

DO DRAWDOWN #1

17:42:00

17:43:00

17:44:00

17:45:00

17:46:00


17:47:00

17:48:00

17:49:00

17:50:00

17:51:00



17:52:00

**END BUILDUP;
PSTOP 1677.40 PSIA**

17:53:00

END PRETEST

17:54:00

FTWD Pressure	
0	3000
lbs / in2 abs	

--

FTWD Remarks

SANTOS Ltd


Galloway-1

FTWD PRESSURE TEST #3 (2135.50 mMDRT / 1186.36 mTVDRT)

FTWD Pressure	
0	3000
lbs / in2 abs	

--

FTWD Remarks



18:20:00

SEND DO FT COMMAND

18:21:00

18:22:00

START PRETEST #3


18:23:00

18:24:00

DO DRAWDOWN #1

18:25:00

18:26:00



18:27:00

18:28:00

18:29:00

18:30:00

18:31:00

18:32:00

18:33:00

18:34:00

SEND END BUILDUP

**END BUILDUP;
PSTOP 1688.67 PSIA**

END PRESTEST

FTWD Pressure

0 3000

lbs / in2 abs

FTWD Remarks

SANTOS Ltd

Galloway-1


FTWD PRESSURE TEST #4 (2146.86 mMDRT / 1197.43 mTVDRT)

FTWD Pressure


0 3000

lbs / in2 abs

FTWD Remarks



18:41:00



18:42:00

SEND DO FT COMMAND

18:43:00

18:44:00

START PRETEST #4

18:45:00

18:46:00

DO DRAWDOWN #1

18:47:00

18:48:00

18:49:00

18:50:00

18:51:00

SEND END BUILDUP

18:52:00

**END BUILDUP;
PSTOP 1703.73 PSIA**

18:53:00

18:54:00

END PRETEST

18:55:00

FTWD Pressure

0

3000

FTWD Remarks

lbs / in2 abs

SANTOS Ltd

Galloway-1

FTWD PRESSURE TEST #5 (2161.0 mMDRT / 1211.29 mTVDRT)

FTWD Pressure

0

3000

FTWD Remarks

lbs / in2 abs

19:14:00

19:15:00

SEND DO FT COMMAND

19:16:00


19:17:00

19:18:00

19:19:00

19:20:00

19:21:00




19:22:00
19:23:00
19:24:00
19:25:00
19:26:00
19:27:00
19:28:00
19:29:00
19:30:00
19:31:00
19:32:00

RESEND DO FT COMMAND

START PRETEST #5

DO DRAWDOWN #1

SEND END BUILDUP



19:33:00
 19:34:00
 19:35:00
 19:36:00

**END BUILDUP;
 PSTOP 1723.20 PSIA**

END PRETEST

FTWD Pressure
0 3000
lbs / in2 abs

FTWD Remarks


SANTOS Ltd

Galloway-1

FTWD PRESSURE TEST #6 (2183.97 mMDRT / 1233.94 mTVDRT)

FTWD Pressure
0 3000
lbs / in2 abs

FTWD Remarks




20:03:00
 20:04:00
 20:05:00
 20:06:00
 20:07:00
 20:08:00

SEND DO FT COMMAND

START PRETEST #6

DO DRAWDOWN #1



20:09:00

20:10:00

20:11:00

20:12:00

20:13:00

20:14:00

20:15:00

20:16:00

SEND END BUILDUP

*END BUILDUP;
PSTOP 1755.20 PSIA*

END PRETEST

FTWD Pressure

0 3000

lbs / in2 abs

FTWD Remarks

SANTOS Ltd

Galloway-1


FTWD PRESSURE TEST #7 (2207.02 mMDRT / 1256.81 mTVDRT)

FTWD Pressure

0 3000


lbs / in2 abs

FTWD Remarks



20:16:00

20:17:00



20:40:00

SEND DO FT COMMAND

20:41:00

20:42:00

20:43:00

20:44:00

RESEND DO FT COMMAND

20:45:00

20:46:00

START PRETEST #7

20:47:00


DO DRAWDOWN #1

20:48:00

20:49:00

20:50:00

20:51:00



20:52:00

20:53:00

20:54:00

20:55:00

SEND END BUILDUP

**END BUILDUP;
PSTOP 1785.80 PSIA**

END PRETEST

FTWD Pressure	
0	3000
<i>lbs / in2 abs</i>	

FTWD Remarks


SANTOS Ltd

Galloway-1

FTWD PRESSURE TEST #8 (2261.51 mMDRT / 1311.21 mTVDRT)

FTWD Pressure	
0	3000
<i>lbs / in2 abs</i>	

FTWD Remarks



22:07:00

22:08:00

22:09:00


22:10:00

22:11:00

SEND DO FT COMMAND

START PRETEST #8

DO DRAWDOWN #1



22:12:00

22:13:00

22:14:00

22:15:00

22:16:00


22:17:00

22:18:00

DRAWDOWN
SEND END BUILDUP

END BUILDUP;
PSTOP 1844.53 PSIA

END PRETEST




FTWD Remarks


SANTOS Ltd

Galloway-1

FTWD PRESSURE TEST #9 (2262.96 mMDRT / 1312.66 mTVDRT)




FTWD Remarks



22:27:00

SEND DO FT COMMAND

22:28:00



22:29:00
 22:30:00
 22:31:00
 22:32:00
 22:33:00
 22:34:00
 22:35:00
 22:36:00
 22:37:00
 22:38:00


START PRETEST #9
DO DRAWDOWN #1
SEND END BUILDUP
**END BUILDUP;
 PSTOP 1846.60 PSIA**
END PRETEST

FTWD Pressure
 0 3000
 lbs / in2 abs

FTWD Remarks

SANTOS Ltd
Galloway-1

FTWD PRESSURE TEST #10 (2268.00 mMDRT / 1317.70 mTVDRT)



END PRETEST

22:06:00

FTWD Pressure

0

3000

FTWD Remarks

lbs / in2 abs

SANTOS Ltd

Galloway-1

FTWD PRESSURE TEST #11 (2281.98 mMDRT / 1331.68 mTVDRT)


FTWD Pressure

0

3000

FTWD Remarks

lbs / in2 abs



00:12:00

SEND DO FT COMMAND

00:13:00

START PRETEST #11

00:14:00

00:15:00


00:16:00

DO DRAWDOWN #1

00:17:00

00:18:00

00:19:00



00:20:00

DRAWDOWN

00:21:00

00:22:00

SEND END BUILDUP

00:23:00

00:24:00

**END BUILDUP;
PSTOP 1874.13 PSIA**

00:25:00

END PRETEST

00:26:00

FTWD Pressure

0 3000

lbs / in2 abs

FTWD Remarks