

From: Simon Rodda /Geoff Webster To: John Ah-Cann

Well Data							
Country	AUSTRALIA	Water Depth(MSL)	155.5m	AFE Cost	\$ 6419132		
Field	VIC-RL6	Water Depth-ASL(MSL)	21.5m	AFE No.	3826-1400		
Rig	OCEAN PATRIOT	RT-Mudline	177.0m	Daily Cost	\$ 1239573		
Days On Ops	3.92			Cum. Cost	\$ 2797471		
Well Objective		Three main Objectives 1. To retrieve, repair and re-run 2. To recover downhole pressul September 2005. 3. To flow test the well to valida	re and temperature		ere installed in		
Current Op @ 0600		Pressure testing SST body and mandrel seals					
Planned Op		Pull ARH plug from hanger and checks and flow test upper zone		SSD, displace tubing to die	esel. Perform pre-flow		
Summary of Peri	od 0000 to 2400 Hrs						

Operations For Period 0000 Hrs to 2400 Hrs on 22 Jun 2006

Phse	Cls (RC)	Ор	From	То	Hrs	Activity Description
PXT	Р	SLK	0000	0030	0.50	RIH with 2.813 XX plug and set in SSD at 2955m. POOH
PXT	Р	PT	0030	0130	1.00	Attempt to pressure test 2.813 plug with no success. Lubricator leaking. Remove lubricator and install test cap and reconfigure surface lines.
PXT	P	PT	0130	0400	2.50	Bleed off control line pressures. Pressure test tubing string to 500 psi/5 min and 4000 psi/10 min against 2.813 plug. Common closed line pressure increased from 0 to 2590 psi. Pressure up on annulus to 1500 psi and monitor ICV and LV control lines pressures. Control line pressures remained constant (DH1-0, DH2=0, DH3=2590psi) Bleed off annulus pressure. Close AMV and AAV. Close SSSV and bleed back tubing head pressure to 500 psi. Perform inflow test on SSSV for 15 minutes. Pressure up tubing to 4000 psi, open SSSV and bleed off tubing pressure. Control line pressures constant. Bleed off control line pressure.
PXT	P	PT	0400	0530	1.50	Remove test cap. Make up lubricator with 4" ARH plug installed. RIH and set ARH in tubing hanger. POOH and make up ARH prong, RIH and set on ARH plug in tubing hanger. POOH with slickline. Pressure test plug and prong to 500 psi/5 min and 5000 psi/10 min. Common close line pressure increased from 0 to 2000 psi during pressure test of ARH plug, but remained at 2000 psi after bleeding off tubing pressure.
PXT	Р	PT	0530	0600	0.50	Rig down slickline lubricator and BOP. Rig down surface lines. Bleed off control line pressures
PXT	Р	WX	0600	0630	0.50	Bleed down common closed control line pressure from 2500 psi to 0 psi. Shut in and monitor pressure build up of 500 psi in 15 minutes. Bleed off pressure and monitor for 15 minutes. 0 psi
PXT	Р	WX	0630	0700	0.50	Unlatch SST from Basker 2 and pick up above guide posts. Observe gas migration from tubing hanger area. Re land and latch SST. Take 50 klb overpull
PXT	Р	WX	0700	0900	2.00	Close PMV and monitor pressures on control lines. DH1=600 psi, DH2=2800 psi, DH3=2800 psi
PXT	Р	ROV	0900	1500	6.00	Shut in SST valves with ROV. Close and test rotary valves to 5000 psi/10 min ROV to surface for repairs and install FLOT
PXT	Р	RU	1500	1900	4.00	Unlatch TRT and lay out FOBV and stiff joint. Move rig off location. Pick up flowhead, install rucker lines, coflex and kill hoses. Install control lines
PXT	Р	WX	1900	2100	2.00	Hold JSA. Move rig over Basker 2. Land and latch TRT on SST. Take 50 klb overpull. Tension ruckers to 4 X 10 klb
PXT	Р	ROV	2100	2400	3.00	Install allpa plate and annulus access line to SST and function subsea tree valves. Rig up slickline BOP and lubricator. Pressure test lubricator and riser against PSV to 500 psi/5 min and 5000 psi/10 min

Operations For Period 0000 Hrs to 0600 Hrs on 23 Jun 2006

Phse	Cls (RC)	Ор	From	То	Hrs	Activity Description
PXT	Р	ROV	0000	0200	2.00	Lower 4 core umbilical on pod line. ROV return to surface and install class II torque tool to open needle valves
PXT	P	wx	0200	0530	3.50	Open Annulus access valve and pressure against AWV and AMV to 500 psi/5 min and 4500 psi/10 min. Install hot stabs to SST and pressure test to 500 psi/5 min and 5000 psi/10 min. Open rotary valves on SST. Conduct VX pressure test 500 psi/5 min and 5000 psi/10 min Conduct SSSV control line pressure test to 7500 psi/10 min Control line pressures;



22 Jun 2006

Phse	Cls (RC)	Op	From	То	Hrs Activity Description								
					DH2	=LV ope	en=0 p	osi					
PXT	Р	PT	0530	0600	DH3=Common close=0 psi Open PSV and PMV. Pressure test SST body and production mandrel seals against ARH plug to 500 psi/5 min and 5000 psi/10 min								
Phase	Data 1	to 2400	hrs, 22	Jun 20		70 P3#0 1	min an	<u>a 0000 psi/10 11</u>					
Phase						Phase	Hrs	Start On	Finish On	Cum Hrs	Cum Days	Max	x Depth
PULL XI	MAS TRI	EE(PXT)					94	13 Jun 2006	22 Jun 2006	94.00	3.917		3414.0n
Bulk S	Stocks												
			Nam	е				Unit	In	Used	Adjust	E	Balance
Barite B	Bulk						MT		0	0	0		46.1
Bentoni	ite Bulk						MT		0	0	0		42.6
Cement	t G						MT		0	0	0		5.7
Cement	t HT (Silid	ca)					MT		0	0	0		93.3
Diesel							m3		0	12	0		368.1
Fresh W	Vater						m3		30	30.8	0		430.0
Drill Wa	nter						m3		0	26	0		667.0
Boa	its	Arrive	d (date/ti	me)	Departed	(date/tin	ne)	Sta	atus		Bulks		
Far Grip	•		21:15 22	Jun 2006				On Standby		Item	Uni		Quantity
										Diesel Fresh Water		m3 m3	493 538
										Drill Water		m3	720
										Cement G Cement HT (Silica)		mt mt	82
										Barite Bulk		mt	85
Pacific								On Ctandby		Bentonite Bulk	11-2	mt	51.3
Wrangle	er							On Standby		ltem Diesel	Uni	m3	Quantity 314.1
										Fresh Water		m3	210
										Drill Water Cement G		m3 mt	74
										Cement HT (Silica)		mt	69
										Barite Bulk Bentonite Bulk		mt mt	19
Perso	nnel O	n Boar	d										
		Job Title)			Perso	nnel			Company			Pax
Operato	or								ANZON AUST	TRALIA LIMITED)	9	
Wellhea	ad Tech								CAMERON A	USTRALIA PTY	LTD	4	
Catering	g								ESS			8	
Cement	ters								DOWELL SCH	HLUMBERGER		2	
ROV									FUGRO ROV	LTD		6	
Contrac	ctor								DOGC			47	
Casing	crew								WEATHERFO	RD AUSTRALIA	A PTY LTD	2	
Testing									EXPRO GRO	UP		14	
Fluid Sa	ampling								PETROLAB		Total	2 94	
HSE S	Summa	ırv											
	Even		Date	e of last	Days Since		De	escr.		Rem	arks		
Abando	n Drill			ın 2006	5 Days								
Fire Dril				ın 2006	5 Days								
JSA				ın 2006	0 Days	Drill cre	ew=6 , 2	Deck=7,					
Man Ov	erboard	Drill	ىل 60	ın 2006	16 Days								
				ın 2006 ın 2006	4 Days	Weekly safety meetings			Hold safety meetings at 1300/1900/0100hrs				
Safety Meeting 18 Jun 2006 STOP Card 22 Jun 2006			0 Days	Safe=5 Un-safe=8									
STOP C	Jaiu					Ou.o-o	011 00						



22 Jun 2006

DAILY WORKOVER REPORT # 5 BASKER - 2 Workover 1

Weather on 22 Jun 2006									
Visibility	Wind Speed	Wind Dir.	Pressure	Air Temp.	Wave Height	Wave Dir.	Wave Period		
10.0nm	30kn	77.0deg	1023.0mbar	15C°	1.5m	77.0deg	4s		
Roll	Pitch	Heave	Swell Height	Swell Dir.	Swell Period	Weather	Comments		
0.4deg	0.3deg	1.0m	2.5m	90.0deg	7s				
Rig Dir.	Ris. Tension	VDL		Comments					
253.0deg	40.00klb	4527.00klb							

Helicopter Movement								
Flight #	Company	Arr/Dep. Time	Pax In/Out	Comment				
1	BRISTOW HELICOPTERS AUSTRALIA PTY LTD	07:50 / 08:15	11 / 15	Fuel = 4272 litres				