

Comp. Rep. J. Perryman

B J SERVICE (AUSTRALIA) PTY. LTD.

Test No. 1

Tester R.W. Stephens

ROOM 3, THIRD FLOOR, PERRY HOUSE, 131-145 ELIZABETH ST., BRISBANE

Date February 1, 1965

Mud Wt.	10.1	Tool Open		Main Hole Size	8 $\frac{3}{4}$ "
Viscosity	50	Tool Shut-In		Rat Hole Size	
Filter Cake	2/32	Time Shut-In		Top Packer Depth	4771'
Water Loss	7	Initial Shut-In Pres.		Bottom Packer Depth	4825'
Mud Drop		Tool Open		Total Depth	5358' (Driller)
Formation		Initial Flow Pres.		Rubber Size	8"
Recorder No.	2237	Final Flow Pres.		Hole Condition	
Clock Range	12 hrs.	Tool Closed		Pipe Size	4 $\frac{1}{2}$ " I.F.
Depth	4760'	Time Shut-In		D.C. Size	2 13/16" I.D.
Recorder No.	2238	Final Shut-In Pres.		Ft. D.C. Run	267
Clock Range	24 hrs.	Initial Hydro Mud Pres.		Water Cushion Run	
Depth	4818'	Final Hydro Mud Pres.		Bottom Hole Choke	$\frac{1}{2}$ "
B.H. Temperature	N.R.	Type Test	Single Straddle	Surface Choke	

Remarks Tool could not be run to bottom - Hung up when bullnose approx. 3650' - Pulled tool from hole without testing


DEPT. NAT. RES & ENV



PE906181

Recovery

WOODSIDE (LAKE ENTRANCE) OIL CO. FEBRUARY 1, 1965
WOODSIDE SEASPRAY NO.2 TEST NO.1
RECORDER NO.2237 RECORDER DEPTH 4760'



WOODSIDE (LAKE ENTRANCE) OIL CO. FEBRUARY 1, 1965
WOODSIDE SEASPRAY NO.2 TEST NO.1
RECORDER NO.2238 RECORDER DEPTH 4818'

