



# Improvement / Incident Details



Generated on Monday, 17 August 2009

## Incident

**Ref No:** NM-142

**Status:** Pending

**Type:** Near Miss

## Identification Details

**Name:** Spriggs, John

**ID No:** 57

**External:**

**Location:** Unspecified

**Source:**

**Grid Ref:**

**Reported:** 23 Jul 2009

**Job No:**

## Incident Date/Time/Location

**Date:** 23 Jul 2009

**Time:** 04:00 PM

**Address:** corner Edmonston & Abbott rds

**Location:** Unspecified

**State/Ctry:** VIC

**Region:** Australia

**Site Type:** Rig 6-TLD

## Incident / Improvement Details

**Category:** Improper Use

**Level:** 1

**Severity:** Insignificant

**Summary:** Slipped while loading HW 3s on Rod Truck

**Description:** JS was putting HW 3s on rod truck for casing, slipped on PVC casing around site while carrying 3m, fell backwards and rod landed on left leg. No injury sustained.

**Injury:**  **Near Miss:**  **Improvement:**  **Environmental:**  **Manual Handling:**  **Asset Damage:**

**Contractor:**

**Employees:**

**Contractors:**

**Division:** Titeline Drilling

**Function:**

**Task:**

**Contract No:**

**Risk Assess:**

**Audit No:**

**Costing:**

**Plan. Project:**

**Proj. Phase:**

**Project Task:**

**Assigned To:** Arthur, Justin

**Delegate:**

**Assigned Date:** 03 Aug 2009

**Action By Date:**

**Close-off Date:**

## Investigation Details

**Cause Cat:**

**Equip No:**

**Plant No:**

**Cause Desc:**

**Likelihood:**

**Conseq:**

**Re-occur Rat:**

**Exposure:**

**Persons:**

**Risk No:**

**Report Doc:**

**Survey Answers:**

**Survey Rating:**

**Answering Employee:**