

WELL NAME *Megascolides-2*

Report at: 09 January 2007 @ 0600hrs

WELL TYPE: APPRAISAL

Rig on Contract: 29 October 2006 @ 1600hrs

WELL AREA: PEP 162 / EL 4537


Spudded: 04 January 2007 @ 1400hrs

RIG: CENTURY RIG 11

Reached TD:

RIG TYPE: LAND RIG ROTARY DRIVE

Rig Released:



A - Delay in spud while repair drawworks bearing  
B - Casing stabbing board not functioning  
C - PVT system being repaired.  
D Bit change - worn  
E Bit change - hard formation  
F Short wiper trip  
G Bit change - worn  
H 0830 Friday 26/1/07

Planned Actual If DST performed If Deepen