## . ... . ....

E/	APL Wellwork & Drilling Daily Ope	rations Report	
Daily Operations: 24 HRS	to 28/08/2007 05:00		
Well Name Fortescue A9b			
Rig Name	Company		
Rig 175	International Sea Drilling LTD (ISDL)		
Primary Job Type	Plan		
Drilling and Completion Target Measured Depth (ftKB)	D&C Target Depth (TVD) (ftKB)		
12,223.9	8,129	.7	
AFE or Job Number	Total Original AFE Amount	Total AFE Supplement Amount	
L0501H008 Daily Cost Total	10,812,892	Currency	
558,672	4,410,197	AUD	
Report Start Date/Time 27/08/2007 05:00	Report End Date/Time 28/08/2007 05:00	Report Number 13	
Management Summary		-	
cement head & HP lines. Circulate slurry. Displace cement w/ 457 bbls	. Held trip drill. Complete RIH w/ 7" production casing string from 1.5x casing volume while prepare for cementing. Cement 7" pro- ISW. Bump plug w/ 2500 psi & hold pressure for 2 mins. Bleed	duction casing w/ 29.2 bbls of 15.8 ppg AB G cement	
Activity at Report Time WOC.			
Next Activity Prepare decks to offload completion	n tubing & equipment. Prepare to cut casing & install piggyback	wellhead spool.	
Daily Operations: 24 HRS t Well Name	to 28/08/2007 06:00		
Cobia F4			
Rig Name	Company		
Rig 22	Imperial Snubbing Services		
Primary Job Type	Plan		
Workover	Tubing pull workover		
Target Measured Depth (ftKB) 11,647.0	Target Depth (TVD) (ftKB)		
AFE or Job Number	Total Original AFE Amount	Total AFE Supplement Amount	
L0503H015	5,460,000	Curreneu	
Daily Cost Total 69,503	1,062,501	AUD	
Report Start Date/Time 27/08/2007 06:00	Report End Date/Time 28/08/2007 06:00	Report Number 16	
Management Summary			
Continue with rig equipment mainte	nance and painting program.		
Activity at Report Time			
Next Activity			
Complete this stage of the rig equip	ment and painting program		
Daily Operations: 24 HRS	to 28/08/2007 06:00		
Well Name			
Barracouta A3W			
Rig Name	Company		
SHU	Imperial Snubbing Services		
Primary Job Type Well Servicing Workover	Plan Repair ICA cement failure.		
Target Measured Depth (ftKB)	Target Depth (TVD) (ftKB)		
8,764.9			
AFE or Job Number	Total Original AFE Amount	Total AFE Supplement Amount	
L0503E044	5,400,000		
Daily Cost Total	Cumulative Cost	Currency	
42,623 Report Start Date/Time	260,124 Report End Date/Time	AUD Report Number	
27/08/2007 06:00	28/08/2007 06:00	7	
Make up a 2-1/2" powercutter toolst Make up 1-11/16" tubing punch, RI	RST-A log from 1240m back to 1040m, POOH. ring RIH and cut 3-1/2" tubing at 1318m, POOH. Hand punch 3-1/2" tubing at 1050m, POOH.		
Activity at Report Time SDFN			
Next Activity			
Pack up Schlumberger equipment a	and prepare for backloadingR/u HES and secure the well. Com	mence the R/u of the SHU.	

Γ

## EAPL WellWork & Drilling Daily Operations Report

Daily Operations: 24 HRS	to 28/08/2007 06:00		
Well Name			
Flounder A25A			
Rig Name	Company		
Wireline	Halliburton / Schlumberger		
Primary Job Type	Plan		
Workover PI	RST-A Log, Plug and Perforate		
Target Measured Depth (ftKB)	Target Depth (TVD) (ftKB)		
11,658.1	······································		
AFE or Job Number	Total Original AFE Amount	Total AFE Supplement Amount	
L0503H038	345,000		
Daily Cost Total	Cumulative Cost	Currency	
20,222	142,708	AUD	
Report Start Date/Time	Report End Date/Time	Report Number	
27/08/2007 06:00	28/08/2007 06:00	7	
Management Summary			
	tch Schlumberger toolstring at 3068m & jar up 1200lb	s, unable to pull. Run 2.25" blind box, jar down and knock fish to	
bottom, tag at 3552m. Rig down H	ES lubricator. Rig up Schlumberger lubricator and pre	ssure test. Lay down lubricator and shut down for night.	
Activity at Report Time			
Prepare to perforate well.			
Next Activity			
Schlumberger perforate well and s	et MPBT plug.		
<b>Daily Operations: 24 HRS</b>	to 28/08/2007 06:00		
Well Name			
Bream B13			
Rig Name	Company		
Wireline	Halliburton / Schlumberger		
Primary Job Type	Plan		
Well Servicing Workover	Remove and replace Xmas tree		
Target Measured Depth (ftKB)	Target Depth (TVD) (ftKB)		
AFE or Job Number	Total Original AFE Amount	Total AFE Supplement Amount	
46000482	80,000		
Daily Cost Total	Cumulative Cost	Currency	
16.370	16,370	AUD	
Report Start Date/Time	Report End Date/Time	Report Number	
27/08/2007 06:00	28/08/2007 06:00	1	
Management Summary			
Change out the Flange on the BOI	D's, Start rigging up on the well,Pressure test as per th of the well.Set and test 2.75" POP test all OK.	e WellWork procedure, Take control of the TR-SSV, Pump 1.5 times	
Activity at Report Time			
SDFN			
Next Activity			
· · · · · · · · · · · · · · · · · · ·		alves, start to circulate the well clean. ready to remove the Wellhead.	